WEAR
CONTAMINATION
FLUID CONDITION


SEVERE NORMAL ATTENTION

[SWA563649]

TERRAMAC RT14R 14RH00107

Top Swing Drive

RECOMMENDATION We recommend that you drain the oil from the component if this has not already been done. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition.	Test	UOM	Method	Limit/Abn	Current	History1	History2
	Sample Number		Client Info		VCP435739		
	Sample Date		Client Info		24 May 2024		
	Machine Age	hrs	Client Info		2703		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		N/A		
	Sample Status				SEVERE		
WEAR	Iron	ppm	ASTM D5185m	>400	146		
Bearing and/or bushing wear is indicated.	Chromium	ppm	ASTM D5185m	>10	0		
	Nickel	ppm	ASTM D5185m	>10	0		
	Titanium	ppm	ASTM D5185m		0		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>25	1		
	Lead	ppm	ASTM D5185m	>50	<1		
	Copper	ppm	ASTM D5185m	>200	4 920		
	Tin	ppm	ASTM D5185m	>10	7		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>50	7		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m	>20	7		
	Water		WC Method	>0.2	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		12		
The oil viscosity is lower than normal. Confirm oil type. The oil is no longer serviceable as a result of the abnormal and/or severe wear.	Boron	ppm	ASTM D5185m	379	11		
	Barium	ppm	ASTM D5185m	0.0	3		
	Molybdenum	ppm	ASTM D5185m	0.8	84		
	Manganese	ppm	ASTM D5185m	0.0	5		
	Magnesium	ppm	ASTM D5185m	31	5		
	Calcium	ppm	ASTM D5185m	38	18		
	Phosphorus	ppm	ASTM D5185m	1077	521		
	Zinc	ppm	ASTM D5185m	46	363		
	Sulfur	ppm	ASTM D5185m	23526	2312		
	Visc @ 40°C	cSt	ASTM D445	139	33.0		





Certificate L2367

Laboratory Sample No.

: VCP435739 Lab Number : 06197066 Unique Number : 11059189 Test Package : MOB 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 31 May 2024 **Tested** : 04 Jun 2024

Diagnosed

: 04 Jun 2024 - Don Baldridge

5985 COURT STREET ROAD SYRACUSE, NY US 13206

ALTA EQUIPMENT

Contact: JIM STRIGLE JIM.STRIGLE@ALTG.COM T: (315)437-2611

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (315)434-9471