



Machine Id VOLVO ECR145 316780 Component

Rear Left Final Drive

GEAR OIL SAE 85W140 (--- GAL)

RECOMMENDATION

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.

V	N	F	Δ	R
		-		

The tin level is abnormal. All other component wear rates are normal.

CONTAMINATION

There is no indication of any contamination in the oil.

FLUID CONDITION

The condition of the oil is acceptable for the time in service.

-/						
Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		VCP439886		
Sample Date		Client Info		11 Jun 2024		
Machine Age	hrs	Client Info		516		
Oil Age	hrs	Client Info		0		
Filter Age	hrs	Client Info		0		
Oil Changed		Client Info		Changed		
Filter Changed		Client Info		Not Changd		
Sample Status				ABNORMAL		
Iron	ppm	ASTM D5185m	>500	317		
Chromium	ppm	ASTM D5185m	>10	6		
Nickel	ppm	ASTM D5185m	>10	<1		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	1		
Lead	ppm	ASTM D5185m	>25	<1		
Copper	ppm	ASTM D5185m	>50	<1		
Tin	ppm	ASTM D5185m	>10	4 23		
Vanadium	ppm	ASTM D5185m		0		
White Metal	scalar	*Visual	NONE	MODER		
Yellow Metal	scalar	*Visual	NONE	NONE		
Silicon	ppm	ASTM D5185m	>75	16		
Potassium	ppm	ASTM D5185m	>20	1		
Water		WC Method	>0.2	NEG		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>0.2	NEG		
Sodium	ppm	ASTM D5185m		4		
Boron	ppm	ASTM D5185m	400	0		
Barium	ppm	ASTM D5185m	200	<1		
Molybdenum	ppm	ASTM D5185m	12	<1		
Manganese	ppm	ASTM D5185m		4		
Magnesium	ppm	ASTM D5185m	12	1		
Calcium	ppm	ASTM D5185m	150	6		
Phosphorus	ppm	ASTM D5185m	1650	252		
Zinc	ppm	ASTM D5185m	125	31		
Sulfur	ppm	ASTM D5185m	22500	17023		
Viec @ 40°C	cSt	ASTM D445	268	127		


Visc @ 40°C


cSt


ASTM D445 368

Contact/Location: PM Services ? - RIPTAM

137







Contact/Location: PM Services ? - RIPTAM Page 2 of 2