



VOLVO

OIL ANALYSIS REPORT

| | |
|-----------------|---------------|
| WEAR | NORMAL |
| CONTAMINATION | NORMAL |
| FLUID CONDITION | NORMAL |



Area
[SWO-072880 LHOIST]

Machine Id
VOLVO A25G 752382

Component
Diesel Engine

Fluid
VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3 (--- GAL)

RECOMMENDATION

Resample at the next service interval to monitor.

| Test | UOM | Method | Limit/Abn | Current | History1 | History2 |
|----------------|-----|-------------|-----------|--------------------|----------|----------|
| Sample Number | | Client Info | | VCP443974 | --- | --- |
| Sample Date | | Client Info | | 13 Jun 2024 | --- | --- |
| Machine Age | hrs | Client Info | | 2503 | --- | --- |
| Oil Age | hrs | Client Info | | 0 | --- | --- |
| Filter Age | hrs | Client Info | | 0 | --- | --- |
| Oil Changed | | Client Info | | Changed | --- | --- |
| Filter Changed | | Client Info | | Changed | --- | --- |
| Sample Status | | | | NORMAL | --- | --- |

WEAR

All component wear rates are normal.

| | | | | | | |
|--------------|--------|-------------|------|--------------|-----|-----|
| Iron | ppm | ASTM D5185m | >100 | 6 | --- | --- |
| Chromium | ppm | ASTM D5185m | >20 | 0 | --- | --- |
| Nickel | ppm | ASTM D5185m | >2 | 3 | --- | --- |
| Titanium | ppm | ASTM D5185m | | 0 | --- | --- |
| Silver | ppm | ASTM D5185m | >2 | <1 | --- | --- |
| Aluminum | ppm | ASTM D5185m | >25 | 4 | --- | --- |
| Lead | ppm | ASTM D5185m | >40 | 0 | --- | --- |
| Copper | ppm | ASTM D5185m | >330 | 6 | --- | --- |
| Tin | ppm | ASTM D5185m | >15 | <1 | --- | --- |
| Vanadium | ppm | ASTM D5185m | | 0 | --- | --- |
| White Metal | scalar | *Visual | NONE | NONE | --- | --- |
| Yellow Metal | scalar | *Visual | NONE | NONE | --- | --- |

CONTAMINATION











There is no indication of any contamination in the oil.

| | | | | | | |
|------------------|----------|-------------|-------|--------------|-----|-----|
| Silicon | ppm | ASTM D5185m | >25 | 4 | --- | --- |
| Potassium | ppm | ASTM D5185m | >20 | 4 | --- | --- |
| Fuel | % | ASTM D3524 | >6.0 | 0.2 | --- | --- |
| Water | | WC Method | >0.2 | NEG | --- | --- |
| Glycol | | WC Method | | NEG | --- | --- |
| Soot % | % | *ASTM D7844 | >3 | 0.2 | --- | --- |
| Nitration | Abs/cm | *ASTM D7624 | >20 | 8.9 | --- | --- |
| Sulfation | Abs/.1mm | *ASTM D7415 | >30 | 19.0 | --- | --- |
| Silt | scalar | *Visual | NONE | NONE | --- | --- |
| Debris | scalar | *Visual | NONE | NONE | --- | --- |
| Sand/Dirt | scalar | *Visual | NONE | NONE | --- | --- |
| Appearance | scalar | *Visual | NORML | NORML | --- | --- |
| Odor | scalar | *Visual | NORML | NORML | --- | --- |
| Emulsified Water | scalar | *Visual | >0.2 | NEG | --- | --- |

FLUID CONDITION

The BN result indicates that there is suitable alkalinity remaining in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

| | | | | | | |
|------------------|----------|-------------|------|-------------|-----|-----|
| Sodium | ppm | ASTM D5185m | | 4 | --- | --- |
| Boron | ppm | ASTM D5185m | 2.5 | 79 | --- | --- |
| Barium | ppm | ASTM D5185m | 0.0 | 0 | --- | --- |
| Molybdenum | ppm | ASTM D5185m | 0.7 | 96 | --- | --- |
| Manganese | ppm | ASTM D5185m | 0.0 | 1 | --- | --- |
| Magnesium | ppm | ASTM D5185m | 256 | 667 | --- | --- |
| Calcium | ppm | ASTM D5185m | 2057 | 1421 | --- | --- |
| Phosphorus | ppm | ASTM D5185m | 935 | 839 | --- | --- |
| Zinc | ppm | ASTM D5185m | 1223 | 955 | --- | --- |
| Sulfur | ppm | ASTM D5185m | 4079 | 3676 | --- | --- |
| Oxidation | Abs/.1mm | *ASTM D7414 | >25 | 17.0 | --- | --- |
| Base Number (BN) | mg KOH/g | ASTM D2896 | 10 | 7.3 | --- | --- |
| Visc @ 100°C | cSt | ASTM D445 | 15.0 | 12.4 | --- | --- |



Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : VCP443974 **Received** : 20 Jun 2024
Lab Number : 06215414 **Tested** : 24 Jun 2024
Unique Number : 11088278 **Diagnosed** : 24 Jun 2024 - Jonathan Hester
Test Package : MOB 1 (Additional Tests: FuelDilution, PercentFuel, TBN)

COWIN EQUIPMENT COMPANY
 2238 PINSON VALLEY PARKWAY
 BIRMINGHAM, AL
 US 35217
 Contact: BRANTLY CLAY
 bclay@cowin.com
 T:
 F: (205)856-2106

Certificate L2367
 To discuss this sample report, contact Customer Service at 1-800-237-1369.
 * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.
 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)