



WEAR CONTAMINATION FLUID CONDITION

NORMAL

ABNORMAL

NORMAL




Machine Id

JOHN DEERE 650K 1T0650KKLNF418076

Rear Left Final Drive [Fluid and provided] (GAL)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.	Sample Number		Client Info		LEC0048686		
	Sample Date		Client Info		20 Jun 2024		
	Machine Age	hrs	Client Info		501		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		N/A		
	Sample Status				ABNORMAL		
WEAR	PQ		ASTM D8184	>1250	57		
All component wear rates are normal.	Iron	ppm	ASTM D5185m	>750	86		
	Chromium	ppm	ASTM D5185m		2		
	Nickel	ppm	ASTM D5185m	>10	0		
	Titanium	ppm	ASTM D5185m		<1		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>40	6		
	Lead	ppm	ASTM D5185m	>15	0		
	Copper	ppm	ASTM D5185m	>40	<1		
	Tin	ppm	ASTM D5185m	>10	0		
	Vanadium	ppm	ASTM D5185m		<1		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION There is a light concentration of water present in the oil.	Silicon	ppm	ASTM D5185m	>75	21		
	Potassium	ppm	ASTM D5185m	>20	11		
	Water	%	ASTM D6304	>0.075	△ 0.186		
	ppm Water	ppm	ASTM D6304	>750	<u> </u>		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.075	0.2%		
FLUID CONDITION	Sodium	ppm	ASTM D5185m	>51	5		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m		<1		
	Barium	ppm	ASTM D5185m		3		
	Molybdenum	ppm	ASTM D5185m		<1		
	Manganese	ppm	ASTM D5185m		3		
	Magnesium	ppm	ASTM D5185m		101		
	Calcium	ppm	ASTM D5185m		3445		
	Phosphorus	ppm	ASTM D5185m		1051		
	Zinc	ppm	ASTM D5185m		1261		
	Sulfur	ppm	ASTM D5185m		4155		
	V" 0 4000	- 04	AOTA DA45		50 Z		

Visc @ 40°C

52.7





Laboratory Sample No.

Lab Number : 06215987 Unique Number : 11088851

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : LEC0048686

Received **Tested**

: 22 Jun 2024 Diagnosed Test Package : CONST (Additional Tests: KF, PQ)

: 23 Jun 2024 - Don Baldridge

: 20 Jun 2024

US 41465 Contact: Service Manager arnettsexcavation@yahoo.com T: (606)496-6400

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

462 MILL BRANCH RD

SALYERSVILLE, KY