**WEAR** CONTAMINATION **FLUID CONDITION**  **ABNORMAL NORMAL NORMAL** 




## [SWO-072880 LHOIST] VOLVO A25G 752382

Brake {not provided} ( GAL)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
No corrective action is recommended at this time. Resample at the next service interval to monitor.	Sample Number	00	Client Info	2.111071011	VCP443980		
	Sample Date		Client Info		13 Jun 2024		
	Machine Age	hrs	Client Info		2503		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		Not Changd		
	Sample Status				ABNORMAL		
WEAR	Iron	ppm	ASTM D5185m	>50	12		
The copper level is abnormal. All other component wear rates are normal.	Chromium	ppm	ASTM D5185m	>20	0		
	Nickel	ppm	ASTM D5185m	>10	0		
	Titanium	ppm	ASTM D5185m		0		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>30	<1		
	Lead	ppm	ASTM D5185m	>50	3		
	Copper	ppm	ASTM D5185m	>200	<u> </u>		
	Tin	ppm	ASTM D5185m	>20	0		
	Vanadium	ppm	ASTM D5185m		<1		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>50	13		
There is no indication of any contamination in the fluid.	Potassium	ppm	ASTM D5185m		4		
	Water	la la	WC Method		NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	LIGHT		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water		*Visual	>0.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		4		
The condition of the fluid is acceptable for the time in service.	Boron	ppm	ASTM D5185m		116		
	Barium	ppm	ASTM D5185m		1		
	Molybdenum	ppm	ASTM D5185m		1		
	Manganese	ppm	ASTM D5185m		1		
	Magnesium	ppm	ASTM D5185m		11		
	Calcium	ppm	ASTM D5185m		3850		
	Phosphorus	ppm	ASTM D5185m		1290		
	Zinc	ppm	ASTM D5185m		1485		
	Sulfur	ppm	ASTM D5185m		5127		

Visc @ 40°C

43.5

ASTM D445





Certificate L2367

Laboratory Sample No.

: VCP443980 Lab Number : 06216084 Unique Number : 11088948 Test Package : MOB 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 20 Jun 2024 **Tested** : 22 Jun 2024

Diagnosed : 23 Jun 2024 - Don Baldridge

**COWIN EQUIPMENT COMPANY** 2238 PINSON VALLEY PARKWAY

BIRMINGHAM, AL US 35217

Contact: BRANTLY CLAY

bclay@cowin.com

F: (205)856-2106

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)