WEAR CONTAMINATION FLUID CONDITION

NORMAL ABNORMAL NORMAL

[SWO-072880 LHOIST] VOLVO A25G 752382

Transmission (Auto)

DEXRON III (GAL)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
We recommend you service the filters on this component. Resample at the next service interval to monitor.	Sample Number		Client Info		VCP443976		
	Sample Date		Client Info		13 Jun 2024		
	Machine Age	hrs	Client Info		2503		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		Not Changd		
	Sample Status				ABNORMAL		
WEAR	Iron	ppm	ASTM D5185m	>160	1		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m	>5	<1		
	Nickel	ppm	ASTM D5185m	>5	0		
	Titanium	ppm	ASTM D5185m		<1		
	Silver	ppm	ASTM D5185m	>5	0		
	Aluminum	ppm	ASTM D5185m	>50	2		
	Lead	ppm	ASTM D5185m	>50	0		
	Copper	ppm	ASTM D5185m	>225	<1		
	Tin	ppm	ASTM D5185m	>10	0		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	nnm	ASTM D5185m	> 20	3		
Moderate concentration of visible dirt/debris present in the fluid.	Potassium	ppm	ASTM D5185m		1		
	Water	ррпп	WC Method	>0.1	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	▲ MODER		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.1	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		0		
The condition of the fluid is acceptable for the time in service.	Boron	ppm	ASTM D5185m		91		
	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		0		
	Manganese	ppm	ASTM D5185m		0		
	Magnesium	ppm	ASTM D5185m		2		
	Calcium	ppm	ASTM D5185m		54		
	Phosphorus	ppm	ASTM D5185m		196		
	Zinc	ppm	ASTM D5185m		3		
	Sulfur	ppm	ASTM D5185m		1850		
	Visc @ 40°C	cSt	ASTM D445	35.0	31.0		





Certificate L2367

Report Id: VOLVO8528 [WUSCAR] 06216220 (Generated: 06/23/2024 13:52:25) Rev: 1

Laboratory Sample No.

Lab Number : 06216220 Unique Number : 11089084 Test Package : MOB 1

: VCP443976

To discuss this sample report, contact Customer Service at 1-800-237-1369.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received **Tested**

Diagnosed

: 20 Jun 2024 : 23 Jun 2024 : 23 Jun 2024 - Don Baldridge

2238 PINSON VALLEY PARKWAY BIRMINGHAM, AL US 35217

Contact: BRANTLY CLAY

COWIN EQUIPMENT COMPANY

bclay@cowin.com

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (205)856-2106