
**WEAR CONTAMINATION FLUID CONDITION**  **ABNORMAL NORMAL NORMAL** 

Machine Id

## **JOHN DEERE 344P 1LV344PAAZB074949**

**Rear Left Final Drive** 

JOHN DEERE GL-5 80W90 ( GAL)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.	Sample Number		Client Info		JR0222081		
	Sample Date		Client Info		20 Jun 2024		
	Machine Age	hrs	Client Info		430		
	Oil Age	hrs	Client Info		430		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		N/A		
	Sample Status				ABNORMAL		
WEAR	PQ		ASTM D8184	>1250	296		
The copper level is abnormal. All other component wear rates are normal.	Iron	ppm	ASTM D5185m	>750	311		
	Chromium	ppm	ASTM D5185m	>9	6		
	Nickel	ppm	ASTM D5185m	>10	1		
	Titanium	ppm	ASTM D5185m		2		
	Silver	ppm	ASTM D5185m		<1		
	Aluminum	ppm	ASTM D5185m	>40	2		
	Lead	ppm	ASTM D5185m	>15	<1		
	Copper	ppm	ASTM D5185m	>40	<u> </u>		
	Tin	ppm	ASTM D5185m	>10	0		
	Vanadium	ppm	ASTM D5185m		<1		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION  There is no indication of any contamination in the oil.	Silicon	ppm	ASTM D5185m	>75	24		
	Potassium	ppm	ASTM D5185m	>20	2		
	Water		WC Method	>0.075	NEG		
	Silt	scalar	*Visual	NONE	MODER		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.075	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m	>51	6		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m		2		
	Barium	ppm	ASTM D5185m		<1		
	Molybdenum	ppm	ASTM D5185m		<1		
	Manganese	ppm	ASTM D5185m		5		
	Magnesium	ppm	ASTM D5185m		3		
	Calcium	ppm	ASTM D5185m		8		
	Phosphorus	ppm	ASTM D5185m		2528		
	Zinc	ppm	ASTM D5185m		120		
	Sulfur	ppm	ASTM D5185m		28049		
	Visc @ 40°C	cSt	ASTM D445		189		





Laboratory Sample No.

Lab Number : 06220057

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : JR0222081

Received **Tested** Diagnosed Unique Number : 11098254 Test Package : CONST ( Additional Tests: PQ )

: 25 Jun 2024 : 26 Jun 2024

: 27 Jun 2024 - Sean Felton

JRE - GARNER 4161 AUBURN CHURCH RD GARNER, NC

US 27529 Contact: RALEIGH SHOP

F: (919)779-5432

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. sean.betts@jamesriverequipment.com;catherine.anastasio@wearcheck.com T: (919)614-2260

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Contact/Location: RALEIGH SHOP - RWMGAR