

WEAR CONTAMINATION **FLUID CONDITION**

NORMAL SEVERE ABNORMAL

MSE-AL-TRACTOR (NEW SOUTH EXPRESS)

AUTOCAR NSE21005 Component Diesel Engine

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
	Sample Number		Client Info		NL0002208	NL0002154	NL0001534
We advise that you check the fuel injection system. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.	Sample Date		Client Info		03 Jul 2024	05 Apr 2024	06 Apr 2023
	Machine Age	hrs	Client Info		12982	11984	7385
	Oil Age	hrs	Client Info		519	1540	1602
	Filter Age	hrs	Client Info		519	0	1602
	Oil Changed		Client Info		Changed	Changed	Changed
	Filter Changed		Client Info		Changed	Changed	Changed
	Sample Status				SEVERE	NORMAL	NORMAL
WEAR	Iron	ppm	ASTM D5185m	>100	42	58	74
	Chromium	ppm	ASTM D5185m	>20	4	3	3
All component wear rates are normal.	Nickel	ppm	ASTM D5185m	>4	1	<1	<1
	Titanium	ppm	ASTM D5185m		0	<1	0
	Silver	ppm	ASTM D5185m	>3	0	0	0
	Aluminum	ppm	ASTM D5185m	>20	17	22	10
	Lead	ppm	ASTM D5185m		0	<1	0
	Copper	ppm	ASTM D5185m		<1	2	1
	Tin	ppm	ASTM D5185m	>15	<1	<1	<1
	Vanadium	ppm	ASTM D5185m	NONE	0	<1	0
	White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
<u></u>	Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
CONTAMINATION	Silicon	ppm	ASTM D5185m	>25	5	7	5
	Potassium	ppm	ASTM D5185m	>20	6	31	18
There is a high amount of fuel present in the oil. Tests confirm the presence of fuel in the oil.	Fuel	%	ASTM D3524	>5	14.8	<1.0	<1.0
	Water		WC Method	>0.2	NEG	NEG	NEG
	Glycol		WC Method		NEG	NEG	NEG
	Soot %	%	*ASTM D7844		1	2	2.8
	Nitration	Abs/cm	*ASTM D7624	>20	11.2	14.3	14.3
	Sulfation	Abs/.1mm	*ASTM D7415		21.1	27.0	26.8
	Silt	scalar	*Visual	NONE	NONE	NONE	NONE
	Debris Sand/Dirt	scalar scalar	*Visual	NONE NONE	NONE NONE	NONE NONE	NONE
	Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
	Odor	scalar	*Visual	NORML	NORML	NORML	NORML
	Emulsified Water			>0.2	NEG	NEG	NEG
FLUID CONDITION	Sodium	ppm	ASTM D5185m		2	<1	1
The BN result indicates that there is suitable alkalinity remaining in the oil. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.	Boron	ppm	ASTM D5185m		2	6	0
	Barium	ppm	ASTM D5185m		0	1	0
	Molybdenum	ppm	ASTM D5185m		49	57	58
	Manganese	ppm	ASTM D5185m		<1	1	<1
	Magnesium Calcium	ppm	ASTM D5185m ASTM D5185m		788 901	844 1170	892 1030
	Phosphorus	ppm	ASTM D5185m		901	994	951
	Zinc	ppm	ASTM D5185m		922 1110	1176	1176
	ZII 10	ppiii					
	Sulfur	nnm	ASTM D5185m		3211	2891	2634
	Sulfur Oxidation	ppm Abs/.1mm	*ASTM D7414	>25	3211 19.4	2891 25.1	2634
	Sulfur Oxidation Base Number (BN)	Abs/.1mm	*ASTM D7414	>25	3211 19.4 7.3	2891 25.1 5.9	2634 23.0 5.2


Visc @ 100°C cSt

ASTM D445

13.8

11.1

14.6







Certificate L2367

Laboratory Sample No.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : NL0002208 Lab Number : 06231881

Unique Number : 11115374

Received

Tested Diagnosed Test Package: FLEET (Additional Tests: FuelDilution, PercentFuel)

: 12 Jul 2024

: 09 Jul 2024

: 12 Jul 2024 - Wes Davis To discuss this sample report, contact Customer Service at 1-800-237-1369.

601 England Rd. Lincoln, AL US 35096 Contact: Skip Womack shop49@knl.cc T: (205)548-3004

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (205)548-3006