
WEAR CONTAMINATION FLUID CONDITION

ABNORMAL NORMAL NORMAL

Machine Id

HITACHI 512576

Component Diesel Engine							
{not provided} (GAL)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
No corrective action is recommended at this time. Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.	Sample Number		Client Info		JR0220324		
	Sample Date		Client Info		08 Jul 2024		
	Machine Age	hrs	Client Info		3256		
	Oil Age	hrs	Client Info		3256		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		Changed		
	Sample Status				ABNORMAL		
WEAR	Iron	ppm	ASTM D5185m		15		
The copper level is abnormal. In the absence of other significant wear metals, suspect copper due to sources other than wear (i.e. cooling core). All other component wear rates are normal.	Chromium	ppm	ASTM D5185m	>20	<1		
	Nickel	ppm	ASTM D5185m	>4	<1		
	Titanium	ppm	ASTM D5185m		<1		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m		7		
	Lead	ppm	ASTM D5185m	>40	<1		
	Copper	ppm	ASTM D5185m		459		
	Tin	ppm	ASTM D5185m	>15	2		
	Vanadium	ppm	ASTM D5185m		<1		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	0:11:		AOTM DE40E	05	-		
	Silicon	ppm	ASTM D5185m		7		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m		2		
	Fuel		WC Method	>5	<1.0		
	Water	0/	WC Method	>0.2	NEG		
	Glycol	%	*ASTM D2982	0	NEG		
	Soot %	%	*ASTM D7844		0.6		
	Nitration	Abs/cm	*ASTM D7624	>20	8.0		
	Sulfation	Abs/.1mm	*ASTM D7415		20.0		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML NORML	NORML		
	Odor Emulsified Water	scalar	*Visual	>0.2	NORML NEG		
	Emuisined water	Scalar	visuai	>0.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		2		
	Boron	ppm	ASTM D5185m		- 11		
The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		68		
	Manganese	ppm	ASTM D5185m		1		
	Magnesium	ppm	ASTM D5185m		958		
	Calcium	ppm	ASTM D5185m		1231		
	Phosphorus	ppm	ASTM D5185m		1056		
	Zinc	ppm	ASTM D5185m		1306		
	Sulfur	ppm	ASTM D5185m		3034		
	Oxidation	Abs/.1mm	*ASTM D7414	>25	15.4		
	Base Number (BN)				9.0		
	Visc @ 100°C	cSt	ASTM D445		13.2		







Certificate L2367

Laboratory Sample No.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : JR0220324 Lab Number : 06232035

Received **Tested** Unique Number: 11115528 Test Package : CONST (Additional Tests: Glycol, TBN)

Diagnosed

: 11 Jul 2024 : 11 Jul 2024 - Don Baldridge

: 10 Jul 2024

JRE - CHARLOTTE 9550 STATESVILLE ROAD CHARLOTTE, NC US 28269

Contact: CHARLOTTE SHOP myoung@jamesriverequipment.com T: (704)597-0211

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (704)596-6198