



OIL ANALYSIS REPORT

WEAR
CONTAMINATION
FLUID CONDITION

NORMAL SEVERE ABNORMAL

Area

(00000)

HINO 8464634

Diesel Engine

MOBIL 15W40 ( QTS)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
HEOCIMIENDATION	Sample Number	OOW	Client Info	LIIII(/ toll	RPL0021892		
We advise that you check the fuel injection system. The oil is near the end of it's useful service life, recommend schedule an oil change. We recommend an early resample to monitor this condition.	Sample Date		Client Info		29 Jun 2024		
	Machine Age	mls	Client Info		142322		
	Oil Age	mls	Client Info		0		
	Filter Age	mls	Client Info		0		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		Changed		
	Sample Status				SEVERE		
WEAR	Iron	ppm	ASTM D5185m		20		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m		<1		
	Nickel	ppm	ASTM D5185m	>4	0		
	Titanium	ppm	ASTM D5185m		0		
	Silver	ppm	ASTM D5185m		<1		
	Aluminum	ppm	ASTM D5185m		4		
	Lead	ppm	ASTM D5185m		3		
	Copper	ppm	ASTM D5185m		3		
	Tin	ppm	ASTM D5185m	>15	1		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION  There is a high amount of fuel present in the oil. Tests confirm the presence of fuel in the oil.	Silicon	ppm	ASTM D5185m	>25	5		
	Potassium	ppm	ASTM D5185m		3		
	Fuel	%	ASTM D3524		<b>▲</b> 9.7		
	Water	, , ,	WC Method		NEG		
	Glycol		WC Method	7 0.2	NEG		
	Soot %	%	*ASTM D7844	>3	0.6		
	Nitration	Abs/cm		>20	12.3		
	Sulfation	Abs/.1mm	*ASTM D7415	>30	23.6		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.2	NEG		
FLUID CONDITION  Calcium ppm levels are abnormally low. Visc @ 100°C is abnormally low. The BN result indicates that there is suitable alkalinity remaining in the oil. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.	Sodium	ppm	ASTM D5185m	>118	2		
	Boron	ppm	ASTM D5185m		5		
	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		59		
	Manganese	ppm	ASTM D5185m		<1		
	Magnesium	ppm	ASTM D5185m		898		
	Calcium	ppm	ASTM D5185m		<u> </u>		
	Phosphorus	ppm	ASTM D5185m		932		
	Zinc	ppm	ASTM D5185m		1185		
	Sulfur	ppm	ASTM D5185m		3567		

Oxidation

Visc @ 100°C cSt

Abs/.1mm \*ASTM D7414 >25


ASTM D445

Base Number (BN) mg KOH/g ASTM D2896

23.7

5.8

11.0





Certificate L2367

Laboratory Sample No.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : RPL0021892 Lab Number : 06234466

Unique Number : 11123300 Test Package: FLEET (Additional Tests: FuelDilution, PercentFuel)

Received : 12 Jul 2024 **Tested** Diagnosed

: 16 Jul 2024 : 16 Jul 2024 - Wes Davis

7837 Telegraph Rd

Contact: GERARDO CARROLA carrolag@rushenterprises.com T:

RTL PACLEASE - 7006 - Pico Rivera

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Pico Rivera, CA

US 90660

F: