


LINE 2 HOT OIL SYSTEM


Customer: PTRHTF10059	System Information	Sample Information
CERTAINTEED - SAINT GOBAIN	System Volume: 1265 gal	Lab No: 02212716
11519 US RT 250 N	Bulk Operating Temp: 460F / 238C	Analyst: Gaston Arseneault
MILAN, OH 44846 USA	Heating Source:	Sample Date: 04/19/18
Attn: DAVE BLAKELY	Blanket:	Received Date: 04/27/18
Tel: (419)541-0843	Fluid: PETRO CANADA CALFLO AF	Completed: 04/30/18
E-Mail: dave.l.blakely@saint-gobain.com	Make: FIRST THERMOL	To discuss this report contact Gaston
		Arseneault at 973-986-6503

Recommendation: The condition of the oil looks very good. Please continue to sample at the same 8-9 months frequency.


Comments:

Sample Date	Received Date	Fluid Age	Sample Location	Flash Point (COC)	Water (KF)	Viscosity (40°C)	Acid Number	Solids	GCD 10%	GCD 50%	GCD 90%	GCD % < 335°C
	mm/dd/yy			°F/°C	ppm	cSt	mg/KOH/ g	%wt	°F/°C	°F/°C	°F/°C	%
04/19/18	04/27/18	Oy	OFF OF HEADER	410 / 210	6.1	31.9	0.02	0.277	690 / 365	790 / 421	883 / 473	2.28
07/12/17	07/28/17	0y		419 / 215	18.5	31.8	0.01	0.314	697 / 369	794 / 424	896 / 480	1.38
07/07/17	07/28/17	Oy		406 / 208	15.1	32.0	0.01	0.289	696 / 369	794 / 423	895 / 479	1.43
02/07/17	02/15/17	0y	SIDE STREAM FLTR PRT	410 / 210	8.7	32.2	0.05	0.145	696 / 369	793 / 423	900 / 482	1.18
05/29/16	06/07/16	Oy	SEALNAT USE TANK PMP	406 / 208	13.7	32.3	0.219	0.156	692 / 367	780 / 416	877 / 469	0.13
02/29/16	03/10/16	Oy	LINE 2 COATER AREA	417 / 214	8.3	33.4	0.22	0.091	692 / 367	792 / 422	899 / 482	1.69
		Baseline	Data	435 / 224		32.7	0.03		693 / 367	790 / 421	887 / 475	2.5






Flash Point (°C)






Elemental anaysis results (above) in parts per million (ppm). [10,000 ppm = 1.0%]



% Boiling < 335°C



Historical Comments

07/12/17	Everything looks excellent, nothing is flagged. Pls resample at next scheduled interval.
07/07/17	Everything looks excellent, nothing is flagged. Pls resample at next scheduled interval.
02/07/17	The age of the fluid is unknown but it showed as 14 years old in 2014. The fluid looks very dark but its condition doesn't look that bad. We do not want to condemn 1200 gals of fluid based on looks only but if problems described last year with deposits in piping in low lying areas then a good system cleaning to restore its overall good condition should be considered.
05/29/16	The fluid looks very dark but its condition is not as bad as in 2014. Solids are not alarmingly high, oxidation is present but not at levels worth flagging or indicative of major problems. It came to our attention however that the system shows deposits in low lying piping and those signs should not be ignored. This oil analysis is just another tool in the toolbox but the challenge is to determine what the inside looks like based on a 1qt sample of hot oil.
02/29/16	Oil is in good condition, no issues at this time. Re-sample at next scheduled interval.

Petro-Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it. Petro-Canada is a division of HollyFrontier Corporation.