

[SUNCOR MACKAY RIVER] TANK 750

Customer: PTRHTF20196

SUNCOR ENERGY MACKAY RIVER PROJECT DOCK M

FORT MCMURRAY, AB T9H 4W1

Canada

Attn: Patrick Spargo Tel: (780)792-2977

System Information

System Volume: 13000 ltr

Bulk Operating Temp: 518F / 270C

Heating Source:

Blanket:

Fluid: PETRO CANADA CALFLO HTF

Make:

Sample Information


Lab No: 02224420 Analyst: Benjamin Latorre Sample Date: 06/14/18 Received Date: 06/26/18 Completed: 09/04/18

To discuss this report contact Benjamin

Latorre at (587)275-0499

Recommendation: 1. Vent the expansion tank regularly to reduce water contaminants and low boilers.2. Pentane Insolubles and Acid Number are low/normal.3. Resample periodically to check on trending of test values.

Comments: Wear metals are low/normal. Water contamination levels are marginally high.











Sample Date	lron	Chromium	Nickel	Aluminum	Copper	Lead	Tin	Cadmium	Silver	Vanadium	Silicon	Sodium	Potassium	Titanium	Molybdenum	Antimony	Manganese	Lithium	Boron	Magnesium	Calcium	Barium	Phosphorus	Zinc
06/14/18	0	0	0	0	0	0	0	0	0	0	5	0	0	0	0	0	0	0	0	1	0	0	12	0
06/13/18	1	0	0	0	0	0	0	0	0	0	7	0	0	0	0	0	0	0	0	1	0	0	16	0
05/31/18	5	0	0	0	0	0	0	0	0	0	7	0	0	0	0	0	0	0	1	0	1	0	84	0
05/17/18	5	0	0	0	0	0	0	0	0	0	7	1	1	0	1	0	0	0	3	0	6	0	292	1
Baseline Data			0	0						0			0	0					0				280	

Elemental analysis results (above) in parts per million (ppm). [10,000 ppm = 1.0%]





Historical Comments 1. Vent the expansion tank regularly to reduce water contaminants.2. Wear metals, Pentane Insolubles and Acid Number are low/normal.3. Resample periodically to check on trending of test values. Water contamination levels are marginally high. Water contamination levels are severely high. Water contamination levels are severely high.. ppm Water contamination levels are severely high. (GCD) 90% Distillation Point is marginally low. 1. Locate and correct source of recurring water contamination. Check heat exchanger for leaks.2. Check low lying areas of the system, such as the expansion tank, where water can be trapped.3. Consider removal of water vapor by venting and addition of nitrogen to the expansion tank head space. Resample initially at 500 hours after correcting source/removal of water contamination. If it has stopped, resample oil at longer intervals. Water contamination levels are severely high. Water contamination levels are severely high. ppm Water contamination levels are severely high.

Petro-Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it. Petro-Canada is a division of HollyFrontier Corporation.