


[VIT E 116] EAST


Customer: PTRHTF10004	System Information	Sample Information
ADM VITAMIN E PLANT	System Volume: 2200 gal	Lab No: 02391629
3700 EAST DIVISION STREET	Bulk Operating Temp: 550F / 288C	Analyst: Joe Goecke
DECATUR, IL 62526 USA	Heating Source:	Sample Date: 11/25/20
Attn: Rick Cluck	Blanket:	Received Date: 12/08/20
Tel: (217)451-7770	Fluid: PETRO CANADA PURITY FG HEAT TRANSFER FLUID	Completed: 12/11/20
E-Mail: ricky.cluck@adm.com	Make: AMERICAN HEATING	Joe Goecke
		Joe.goecke@petrocanadalsp.com

Recommendation: Flash Point just a little low however within operating limits. all other numbers good and system is okay for continued use, resample at next scheduled interval.

Comments: COC Flash Point is marginally low.

Sample Date	Received Date	Fluid Age	Sample Location	Flash Point (COC)	Water (KF)	Viscosity (40°C)	Acid Number	Solids	GCD 10%	GCD 50%	GCD 90%	GCD % < 335°C
	mm/dd/yy			°F/°C	ppm	cSt	mg/KOH/ g	%wt	°F/°C	°F/°C	°F/°C	%
11/25/20	12/08/20	0m	Pump	381 / 194	10.4	29.0	0.54	0.112	702 / 372	809 / 432	910 / 488	4.17
08/25/20	09/03/20	0m	FILTER	313 / 156	19.2	27.7	0.36	0.032	667 / 353	803 / 428	909 / 487	7.07
05/08/20	05/13/20	0m		352 / 178	22.4	32.8	0.51	0.040	707 / 375	810 / 432	910 / 488	3.52
07/29/19	08/08/19	0m	HOT OIL PUMP	343 / 173	12.5	25.2	0.250	0.087	463 / 240	754 / 401	872 / 467	19.51
05/29/19	06/05/19	0m		347 / 175	20.5	26.6	0.259	0.062	657 / 347	796 / 425	909 / 487	7.91





08/25/20	look good. Continue to run until next sample and plan for a possible change at winter shut down. COC Flash Point is severely low.
05/08/20	All parameters are in good shape. Flash point is a little low but okay. continue to use and resample in 90 days. COC Flash Point is abnormally low.
07/29/19	Low Boilers are very high at almost 20%. Flash point not much change or viscosity. Please consider a system change in the next 30-60 days with a resample. (GCD) % < 335°C is severely high. (GCD) 10% Distillation Point is severely low. COC Flash Point is severely low. (GCD) 90% Distillation Point is marginally low.
05/29/19	Low boilers approaching 8% with viscosity and flash points both slightly lower the system is showing some signs of these building up in the system. System is okay for continued use resample in 60-90 days. COC Flash Point is severely low. (GCD) % < 335°C is marginally high. (GCD) 10% Distillation Point is marginally low.

Petro-Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it. Petro-Canada is a division of HollyFrontier Corporation.