


[4-17-51-18W5] UH-5000


Customer: PTRHTF60073	System Information	Sample Information
Tourmaline Oil Corp	System Volume: 19000 ltr	Lab No: 02626250
4-17-51-18W5	Bulk Operating Temp: 500F / 260C	Analyst: Clinton Buhler
5991 3 Ave.	Heating Source:	Sample Date: 03/06/24
Edson, AB T7E 1R8 CA	Blanket:	Received Date: 04/02/24
Attn: Justin Thebeau	Fluid: PETRO CANADA PETRO-THERM	Completed: 04/10/24
Tel: (780)725-1519	Make: RUSHTON	Clinton Buhler
E-Mail:		Clinton.Buhler@HFSinclair.com

Recommendation: Sample results indicate the fluid is in suitable condition for continued service. Solids content is up to 0.253%. Please re-sample in 12 months and carefully purge sample valve before taking sample.

Comments: (GCD) 90% Distillation Point is marginally high.

Sample Date	Received Date	Fluid Age	Sample Location	Flash Point (COC)	Water (KF)	Viscosity (40°C)	Acid Number	Solids	GCD 10%	GCD 50%	GCD 90%	GCD % < 335°C
	mm/dd/yy			°F/°C	ppm	cSt	mg/KOH/ g	%wt	°F/°C	°F/°C	°F/°C	%
03/06/24	04/02/24	9.0y	return line	442 / 228	6	36.3	0.11	0.253	730 / 388	820 / 438	920 / 493	0.47
03/08/23	03/31/23	0.0y	sight glass	424 / 218	13.0	34.9	0.26	0.096	716 / 380	813 / 434	912 / 489	2.32
03/15/22	04/11/22	2.0y	sight glass	439 / 226	171.6	28.7	0.11	0.055	718 / 381	813 / 434	915 / 490	2.10
03/15/21	03/30/21	5.0y	Pump suction	457 / 236	7.2	34.9	0.08	0.051	720 / 382	815 / 435	924 / 496	1.10
01/11/21	01/22/21	6.0y	SITE GLASS	432 / 222	11.1	34.0	0.10	0.080	726 / 386	815 / 435	913 / 490	0.52





Historical Comments				
03/08/23	Sample results indicate that the fluid is in suitable condition for continued service. Resample in 12 months.			
03/15/22	Sample results indicate the fluid is in suitable condition for continued service. Viscosity has been reduced yet flash point, distillation curve and low boiling vapor content are in good condition. Please re-sample in 12 months.			
03/15/21	Fluid remains in excellent condition. No change since previous sample in January 2021. (GCD) 90% Distillation Point is marginally high.			
01/11/21	This fluid appears to be in good condition. Maintain good system maintenance practices and resample in 6 months.			

Percent Recovered

Petro-Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it. Petro-Canada is a division of HollyFrontier Corporation.