

## **NEW DIAMOND STARTCH**

## Customer: PTRHTF60010

SYNLUBE INTERNATIONAL CO LTD 76/1 MOO.7 THACHIN

MUANG SAMUTSAKHON, 74000 TH Attn: CHERNPORN CHOBKUI

Tel: 034421290

E-Mail: chernporn@synlube.co.th

## System Information

System Volume: 10000 ltr

Bulk Operating Temp: 536F / 280C

Heating Source:

Blanket:

Fluid: EASTMAN THERMINOL 55

Make:

## Sample Information

Lab No: 02637566

Analyst: Bill Quesnel CLS,OMA II,MLA-


III,LLA-I

Sample Date: 05/17/24 Received Date: 05/24/24 Completed: 05/29/24


Bill Quesnel CLS, OMA II, MLA-III, LLA-I

Recommendation: We recommend that you vent the expansion tank to remove low boilers which assists in restoring the flash point of the fluid. The fluid is suitable for further service. Resample at the next service interval to monitor.

Comments: Acid Number (AN) is abnormally high. (GCD) 90% Distillation Point is abnormally high. Zinc ppm levels are abnormally high.



Report ID: [02637566] (Generated: 05/29/2024 16:13:27) - Page 1 - Copyright 2024 Wearcheck Inc. All Rights Reserved.



Petro-Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it. Petro-Canada is a division of HollyFrontier Corporation.