

HEATER 2

0.20


0.00

Feb7/21

Customer:	System Information	Sample Information
ASSOCIATED ASPHALT	System Volume: 0 gal	Lab No: 05455335
195 LAWSON FORK ROAD	Bulk Operating Temp: Not Specified	Analyst: Doug Bogart
INMAN, SC 29349 USA	Heating Source:	Sample Date: 01/30/22
Attn: MARSHALL HOWINGTON	Blanket:	Received Date: 01/31/22
Tel: (864)472-2816	Fluid: NOT GIVEN	Completed: 02/10/22
E-Mail:	Make:	Doug Bogart
mhowington@associatedasphalt.com		dougb@wearcheckusa.com

Recommendation: This is a baseline read-out on the submitted sample.

Comments: All metal levels are normal indicating no corrosion in the system. The water content is negligible. There is no indication of any contamination in the fluid. The AN level is acceptable for this fluid.



225

220

Feb7/21

Jan30/22

Jan30/22

Feb7/21

Abnorma

70

60

50

Jan30/22



Elemental anaysis results (above) in parts per million (ppm). [10,000 ppm = 1.0%]

GCD Spectrum

Historical Comments		
02/07/21	This is a baseline read-out on the submitted sample. All component wear rates are normal. The water content is negligible. There is no indication of any contamination in the fluid. The AN level is acceptable for this fluid.	

WearCheck Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it.