





## **THERMINOL 55 USED**

**Customer:** 

TULCO OILS INC (006-NATIONAL

DIVISI...

5240 EAST PINE TULSA, OK 74115 US Attn: MIKE HANN Tel: (800)375-2347

E-Mail:

System Information

System Volume: 0 gal

Bulk Operating Temp: Not Specified

Heating Source:

Blanket:

Fluid: EASTMAN THERMINOL 55

Make:

Sample Information

Lab No: 05724091 Analyst: Doug Bogart Sample Date: 12/21/22 Received Date: 12/22/22 Completed: 01/05/23

Doug Bogart

dougb@wearcheckusa.com

Recommendation: We recommend that you vent the expansion tank to remove low boilers which assists in restoring the flash point of the fluid. We recommend an early resample to monitor this condition. Test(s) for distillation and flash point performed at WearCheck Canada. COC reading is actually PMCC.

Comments: {not applicable} There is no indication of any contamination in the fluid. (GCD) % < 335°C is severely high. (GCD) 10% Distillation Point is severely low. (GCD) 90% Distillation Point is severely low. Pensky-Martens Flash Point is abnormally low.



