

LIEBHERR R934 036784 - Splitter Box

LH0070664

25 Oct 2013 477

Changed NORMAL

Sample No: LH0070664

Oil Type: CHEVRON DELO GEAR ESI OIL 80W90

0

SAMPLE INFORMATION

Sample Number
Sample Date
Machine Hours
Oil Hours
Oil Changed
Sample Status

OIL CONDITION

Visc @ 40°C

.....

cSt **0 192**

	TAMINA	TION		
Silicon	ppm	6	 	
Sodium	ppm	<mark></mark> <1	 	
Potassium	ppm	0 2	 	

WE/	AR META	LS		
Iron	ppm	0 10	 	
-		•		
Copper	ppm	○ <1	 	
Lead	ppm	<mark></mark> <1	 	
Tin	ppm	0 ()	 	
Aluminum	ppm	04	 	
Chromium	ppm	<mark></mark> <1	 	
Molybdenum	ppm	0 🔘	 	
Nickel	ppm	0 ()	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	01	 	
Vanadium	mag	0	 	



ADDITIVES

Calcium	ppm	0 11	 	
Magnesium	ppm	02	 	
Zinc	ppm	0 30	 	
Phosphorus	ppm	1681	 	
Barium	ppm	0 12	 	
Boron	ppm	01	 	





LIEBHERR CANADA LTD.

10374 267 ST. ACHESON, AB CA T7X 6A2 Contact: Rodney Budzak rodney.budzak@liebherr.com T: (780)962-6799 F: (780)962-6799

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the component. The condition of the oil is acceptable for the time in service.

Depot:	LIESPR
Unique No:	3827162
Signed:	Bill Quesnel
Report Date:	12 Nov 2013





Ferrous Alloys

GRAPHS

 \odot

