

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH50M 097459-1216 - Rear Left Wheel Hub

Sample No: LH0180233

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC



J.D. Irving
 Truro Sawmill, 529 Valley Dale Road
 Truro, NS
 CA B2N 5C5
 Contact: Sheldon Richardson
 richardson.sheldon@jdirving.com
 T: (902)890-9419
 F:



SAMPLE INFORMATION

Sample Number	LH0180233	LH	LH0139126	LH0136435
Sample Date	06 Oct 2020	07 Jul 2020	01 Mar 2020	08 Nov 2019
Machine Hours	0	0	13987	12894
Oil Hours	0	0	0	1000
Oil Changed	Changed	Changed	Changed	Changed
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL



OIL CONDITION

Visc @ 40°C	cSt	97.7	91.6	94.3	92.3
-------------	-----	------	------	------	------



CONTAMINATION

Silicon	ppm	2	2	3	1
Sodium	ppm	<1	<1	0	0
Potassium	ppm	<1	1	<1	<1



WEAR METALS

Iron	ppm	12	11	21	14
Copper	ppm	<1	<1	<1	1
Lead	ppm	0	0	0	0
Tin	ppm	0	<1	0	0
Aluminum	ppm	<1	0	<1	<1
Chromium	ppm	0	0	<1	<1
Molybdenum	ppm	<1	<1	0	0
Nickel	ppm	0	<1	<1	<1
Titanium	ppm	0	0	0	0
Silver	ppm	<1	0	0	<1
Manganese	ppm	<1	<1	<1	<1
Vanadium	ppm	0	0	0	0



ADDITIVES

Calcium	ppm	6	5	7	8
Magnesium	ppm	2	1	1	1
Zinc	ppm	5	5	7	6
Phosphorus	ppm	1240	1238	1286	1266
Barium	ppm	0	0	0	0
Boron	ppm	323	308	336	333

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: JDITRU
Unique No: 5122515
Signed: Wes Davis
Report Date: 22 Oct 2020



GRAPHS

