LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR R936 040309-1148 - Right Final Drive

Sample No: LH0192089

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC

ā					
SAM	PLE INFOR	MATION			
Sample Number		LH0192089	LH0119401	LH0110771	LH0092962
Sample Date		17 Nov 2021	07 May 2018	22 Aug 2017	25 Feb 2016
Machine Hours		8375	4983	3907	1139
Oil Hours		0	0	0	0
Oil Changed		Changed	Changed	Changed	Changed
Sample Status		NORMAL	NORMAL	NORMAL	NORMAL
<u> </u>					
OILC	ONDITION	ı			
Visc @ 40°C	cSt	128	O 113	O 133	O 142
Acid Number (AN)	mg KOH/g				0 1.11
*	AMINATI	ION			
Silicon	ppm	44	4 3	O 23	O 7
Sodium	ppm	12	O 12	1 4	O 11
Potassium	ppm	1636	O 1317	1630	○ 804
WEA	R METALS	;			
PQ					O 96
Iron	ppm	200	O 136	O 114	O 121
Copper	ppm	<1	O 2	O <1	O <1
Lead	ppm	0 <1	O <1	O <1	O <1
Tin	ppm	0	O 0	O 0	0
Aluminum	ppm	13	O 12	O 7	3
Chromium	ppm	2	O 2	O 1	O 2
Molybdenum	ppm	0 <1	O 0	O <1	O <1
Nickel	ppm	2	2	1	<1
Titanium	ppm	<1	1	<1	0
Silver	ppm	0	0	0	0
Manganese	ppm	2	O 1	<1	 <1
Vanadium	ppm	<1	<1	0	0
ADDI	TIVES				
Calcium	ppm	77	O 122	9 4	66
Magnesium	ppm	5	O 4	4	21
Zinc	ppm	25	O 104	O 20	O 27
Phosphorus	ppm	454	460	518	O 885

1206



RICHMOND STEEL RECYCLING

11760 MITCHELL ROAD RICHMOND, BC CA V6V 1V8

Contact: Aaron Kaetler AKaetler@richmondsteel.ca

T:

F: (604)324-8617

Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill.

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot:RIC117RICUnique No:5317030Signed:Wes DavisReport Date:19 Nov 2021

02

() <1

1421

ppm

ppm

Barium

Boron





GRAPHS

