**CONSTRUCTION EQUIPMENT** 

## [IRON SHORING] 100-038 - Auxiliary Winch

LH0239474 Sample No:

Oil Type: LIEBHERR SYNTOGEAR PLUS 75W-90

<b>5</b>				
U SAM	PLE INF	ORMATION		
Sample Number		LH0239474	 	
Sample Date		04 Aug 2022	 	
Machine Hours		498	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL	ONDITIO	ON		
Visc @ 40°C	cSt	262	 	
CON	TAMINA	ATION		
Silicon	ppm	<b>152</b>	 	
Sodium	ppm	<b>4</b>	 	
Potassium	ppm	<b>O</b> <1	 	

Potassium	ppm	<b>○</b> <1						
WEAR METALS								
Iron	ppm	<b>40</b>						
Copper	ppm	<b>2</b>						
Lead	ppm	<b>()</b> <1						
Tin	ppm	0						
Aluminum	ppm	61						
Chromium	ppm	<1						
Molybdenum	ppm	<b>0</b>						
Nickel	ppm	<1						
Titanium	ppm	<1						
Silver	ppm	<1						
Manganese	ppm	<b>()</b> <1						
Vanadium	ppm	0						

ADDITIVES							
Calcium	ppm	<b>162</b>					
Magnesium	ppm	<b>15</b>					
Zinc	ppm	91					
Phosphorus	ppm	1123					
Barium	ppm	<b>()</b> <1					
Boron	ppm	<b>1</b>					

Report Id: RONVAU [WCAMIS] 02503781 (Generated: 11/03/2023 11:31:53) Rev: 1





#### RONI/IRON SHORE EXCAVATING LTD.

100 MACINTOSH BLVD VAUGHAN, ON CA L4K 4P3

Contact: Nathan Fernandes nfernandes@roni.ca

T: F:

#### Diagnosis

Resample at the next service interval to monitor. Metal levels are typical for a new component breaking in. There is no indication of any contamination in the oil. Viscosity of sample indicates oil is within SAE 80W140 range, advise investigate. The condition of the oil is acceptable for the time in service.

Depot: **RONVAU Unique No:** 5436742 Signed: Kevin Marson Report Date: 08 Aug 2022

# LIEBHERR







### **GRAPHS**

