CONSTRUCTION EQUIPMENT

LIEBHERR LH50M 097459-1216 - Front Right Wheel Hub

Sample No: LH0250290

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC

5					
	PLE INFO	RMATION			
Sample Number		LH0250290	LH0238569	LH0230416	LH0183922
Sample Date		31 May 2023	24 Oct 2022	05 May 2022	05 May 2022
Machine Hours		26834	1000	22049	22049
Oil Hours		0	0	0	0
Oil Changed		Changed	N/A	Changed	Changed
Sample Status		NORMAL	NORMAL	NORMAL	NORMAL
	ONDITIO	N			
			0.000	0.07.0	0.07.0
Visc @ 40°C	cSt	88.1	90.8	97.9	87.8
CON	TAMINA1	TION			
Silicon	ppm	03	2	02	04
Sodium	ppm	0 2	03	0	0 1
Potassium	ppm	2	0 2	0 <1	0 <1
			0	Ū	0
WEA	R METAL	6			
		<u> </u>		0.45	0.40
Iron	ppm	3 6	0 49	25	0 48
Copper	ppm	07	08	○ <1	07
Lead	ppm	0	0 <1	0	0 <1
Tin	ppm	0	0	0	0
Aluminum	ppm	0 <1	0 <1	0	0 <1
Chromium	ppm	0	0	0	○ <1
Molybdenum	ppm	08	0	0	0 <1
Nickel	ppm	0	0 <1	○ <1	○ <1
Titanium	ppm	0	0	0	0
Silver	ppm	0	0	0	0
Manganese	ppm	0 <1	0 <1	○ <1	○ <1
Vanadium	ppm	0	0	0	0
ADD	ITIVES				
Optoin	ppm	0 156	23	07	0 14
Calcium	1= 1= · · · ·	U	-	0	03
	mag	122	()2		() $()$ $()$ $()$ $()$ $()$ $()$ $()$
Calcium Magnesium Zinc	ppm mag		0 2	○ 2○ 7	-
Magnesium Zinc	ppm	175	0 19	7	0 17
			•	-	-



J.D. Irving

Truro Sawmill, 529 Valley Dale Road Truro, NS CA B2N 5C5 Contact: Sheldon Richardson richardson.sheldon@jdirving.com T: (902)890-9419 F:

Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot:	JDITRU
Unique No:	5590894
Signed:	Wes Davis
Report Date:	05 Jun 2023





GRAPHS

 \bigcirc

