CONSTRUCTION EQUIPMENT

LIEBHERR HS855 184763 - Splitter Box

Sample No: LH0260993

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC





BOISBRAND, QC CA J7E 4H5

Contact: Service Manager

T: (514)694-2200

F:

OIL	CON	DIT	ON

Visc @ 40°C **140**


1

ONTAMINATION

Water	%	NEG	 	
Silicon	ppm	8	 	
Sodium	ppm	1	 	
Potassium	ppm	222	 	



ppm	40			
ppm	3			
ppm	() <1			
ppm	0			
ppm	2			
ppm	0 <1			
ppm	0			
ppm	0 <1			
ppm	<1			
ppm	3			
ppm	() <1			
ppm	0			
	ppm	ppm	ppm	ppm





Calcium	ppm	670	 	
Magnesium	ppm	1	 	
Zinc	ppm	276	 	
Phosphorus	ppm	655	 	
Barium	ppm	0	 	
Boron	ppm	221	 	

Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition.Les taux d'usure de tous les composants sont normaux. Il n'y a aucun indice de contamination dans l'huile. Les niveaux d'additifs indiquent l'ajout d'une autre marque ou d'un autre type d'huile. L'état de l'huile est acceptable pour la durée de service.

Depot: **GEOBOI** Unique No: 5594141 Kevin Marson Signed: **Report Date:** 19 Jun 2023

LIEBHERR







GRAPHS

