LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH40M 098208 - Rear Differential

Sample No: LH

Boron

Oil Type: GEAR OIL SAE 80W90

<u> </u>				
U SAM	PLE INFO	RMATION		
Sample Number		LH	 	
Sample Date		29 Jun 2023	 	
Machine Hours		6242	 	
Oil Hours		135	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
OIL	ONDITIO	N		
Visc @ 40°C	cSt	① 192		
VISC @ 40 C	COL	132	 	
CON	TAMINA1	TION		
Silicon	ppm	3	 	
Sodium	ppm	9	 	
Potassium	ppm	0 <1	 	
◎ WEA	R METAL	S		
		<u> </u>		
Iron	ppm	34	 	
Copper	ppm	○ 55	 	
Tin	ppm	○ 1 ○ 0	 	
Aluminum	ppm	○ <1	 	
Chromium	ppm	0<1	 	
Molybdenum	ppm	00	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	O <1	 	
Vanadium	ppm	0	 	
ADD	ITIVES			
Calcium	ppm	11	 	
Magnesium	ppm	0 1	 	
Zinc	ppm	39	 	
Phosphorus	ppm	2316	 	
Barium	ppm	 <1	 	
_				



LIEBHERR CANADA LTEE 444 AVENUE DE LA FRICHE DOLBEAU-MISTASSINI, QC CA G8L 3M7

Contact: Luc Trottier luc.trottier@liebherr.com

T:

F: (418)276-9844

Diagnosis

Resample at the next service interval to monitor. Please note that this is a corrected copy for data entry updates. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: LBADOL
Unique No: 5605134
Signed: Kevin Marson
Report Date: 20 Jul 2023

3

ppm

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

