CONSTRUCTION EQUIPMENT

LIEBHERR LH60M 145111-1217 - Rear Differential

Sample No: LH0247466

-

Oil Type: GEAR OIL SAE 80W90

SAMPLE INFORMATION

Sample Number		LH0247466	LH0261411	LH0261408		
Sample Date		20 Jun 2023	27 Apr 2023	27 Apr 2023		
Machine Hours		1188	558	558		
Oil Hours		0	0	0		
Oil Changed		Changed	Changed	Changed		
Sample Status		NORMAL	NORMAL	NORMAL		
OIL CONDITION						
Visc @ 40°C	cSt	0 114	0 176	0 169		

Silicon	ppm	04	2	04	
Sodium	ppm	01	0 4	3	
Potassium	ppm	01	◯ <1	◯ <1	

	R METALS				
	-	0.10	0.04		
Iron	ppm	0 12	21	04	
Copper	ppm	0 17	6	6	
Lead	ppm	○ <1	0	0	
Tin	ppm	0 ()	0	0	
Aluminum	ppm	○ <1	○ <1	○ <1	
Chromium	ppm	0 ()	0	0	
Molybdenum	ppm	0	0	0	
Nickel	ppm	○ <1	○ <1	○ <1	
Titanium	ppm	0	0	0	
Silver	ppm	0	0	0	
Manganese	ppm	○ <1	<1	<1	
Vanadium	ppm	0	0	0	

ADDITIVES Calcium 06 ppm 8 8 Magnesium ppm 01 <1 Zinc 10 8 0 17 ppm Phosphorus 0 1336 1376 1442 ppm 284 242 Barium ppm 0 46 Boron 0 268 32 ppm 50





RAM IRON AND METAL

60 Ashwarren Road TORONTO, ON CA M3J 1Z5 Contact: PETER RACCO PETER@RAMIRON.COM T: (416)630-4545 F: (416)630-5258

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:	RAM
Unique No:	560
Signed:	Wes
Report Date:	10 J

AMTOR 605924 es Davis 9 Jul 2023





GRAPHS

 \odot

