# LIEBHERR

**CONSTRUCTION EQUIPMENT** 

## **LIEBHERR R934 048907-1550 - Splitter Box**

Sample No: LH0260442

Oil Type: PETRO CANADA TRAXON SYNTHETIC 75W90

Ō SAME	LE INFOR <i>I</i>	AATION			
	LE INFOR				
Sample Number		LH0260442	LH0226685	LH0191759	LH0177406
Sample Date		07 Jul 2023	16 Mar 2023	26 May 2021	28 Aug 2020
Machine Hours		4540	4080	1513	467
Oil Hours		0	0	0	0
Oil Changed		Changed	Changed	Changed	Changed
Sample Status		ABNORMAL	NORMAL	NORMAL	NORMAL
	NDITION				
Visc @ 40°C	cSt	<b>122</b>	O 146	O 182	O 194
	AMINATIO				
Silicon	ppm	<b>44</b>	<b>4</b>	<b>3</b>	0 1
Sodium	ppm	<b>2</b>	02	<b>4</b>	<b>4</b>
Potassium	ppm	<b>○</b> <1	0 1	O 1	O 2
WEAR METALS					
Iron	ppm	<b>53</b>	○ 32	○ 36	O 25
Copper	ppm	<b>○</b> <1	0 1	02	O <1
Lead	ppm	<b>○</b> <1	0	O <1	O <1
Tin	ppm	<b>0</b>	0	0	0
Aluminum	ppm	<b>2</b>	O 2	O 1	<b>3</b>
Chromium	ppm	<b>○</b> <1	O <1	O <1	<b></b> <1
Molybdenum	ppm	<b>0</b>	0	0	O 0
Nickel	ppm	<b>()</b> <1	0	0	0
Titanium	ppm	<b>0</b>	0	0	0
Silver	ppm	0	0	<1	<1
Manganese	ppm	<b>○</b> <1	<b></b> <1	O <1	<b>1</b>
Vanadium	ppm	0	0	0	0
ADDITIVES					
Calcium	ppm	<b>68</b>	O 104	50	O 13
Magnesium	ppm	<b>2</b>	O <1	O 2	O 2
Zinc	ppm	<b>57</b>	93	40	<b>18</b>
Phosphorus	ppm	<b>1867</b>	2157	<b>1828</b>	O 1482
Barium	ppm	<b>0</b> <1	0	02	<b>4</b>
Boron	ppm	<b>128</b>	01	<b>6</b>	O 1



REGEHR CONTRACTING 6547 MT. LEHMAN ROAD ABBOTSFORD, BC CA V4X 2G5 Contact: Service Manager

Jonaci. Service Man

T: F:

#### Diagnosis

We advise that you check all areas where dirt can enter the system. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition. All component wear rates are normal. There is a moderate concentration of dirt present in the oil. The oil is no longer serviceable due to the presence of contaminants.

Depot: REGABB
Unique No: 5605931
Signed: Kevin Marson
Report Date: 10 Jul 2023

**CONSTRUCTION EQUIPMENT** 





### **GRAPHS**

