ł BHERR **CONSTRUCTION EQUIPMENT**

[IMPERIAL EQUIPMENT] LIEBHERR L580 68394 - Splitter Box

Sample No: LH0266091

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC

-					
	\PLE INFO	DRMATION			Contract of the second
Sample Number		LH0266091	LH0246731	LH0238584	 ~
Sample Date		07 Jul 2023	23 Dec 2022	22 Sep 2022	 LIEBHERR CANADA
Machine Hours		1597	1052	496	 10 LYNDS AVENUE
Oil Hours		0	0	0	 MONCTON, NB
Oil Changed		Changed	N/A	N/A	 CA E1H 3K2
Sample Status		NORMAL	NORMAL	ABNORMAL	 Contact: Mike Clark
					Mike.Clark@liebherr.com T: (506)854-2920
OIL	CONDITIC	DN			F: (506)854-2940
Visc @ 40°C	cSt	93.6	98.1	0 172	
1					Diagnosis
CON	TAMINA	TION			Resample at the next service
Silicon	ppm	04	02	02	 to monitor.All component wea
Sodium	ppm	0 <1	0 <1	03	 are normal. There is no indica
Potassium	ppm	0 <1	0 <1	0	 any contamination in the oil. T
	1-1-	U	0	0	condition of the oil is acceptal
		16			the time in service.
Iron	ppm	0 12	0 21	62	
Copper	ppm	○ <1	0 <1	02	
Lead	ppm	0	0 <1	0 <1	
Tin	ppm	0	0	0	
Aluminum	ppm	0	0 <1	○ <1	
Chromium	ppm	0	0	○ <1	
Molybdenum	ppm	0 <1	0 <1	○ <1	
Nickel	ppm	<mark></mark> <1	○ <1	2	
Titanium	ppm	0	0	0	
Silver	ppm	0	0	0	
Manganese	ppm	◯ <1	0 <1	2	
Vanadium	ppm	0	0	0	
	ITIVES				
Calcium	ppm	8	0 10	0 30	
Magnesium	ppm	0 2	5	07	
Zinc	ppm	0 14	20	65	
Phosphorus	ppm	0 1366	0 1460	2269	
Barium	ppm	0 <1	3	28	
-					



e interval ear rates cation of The able for

Depot:	LIEMON		
Unique No:	5606511		
Signed:	Wes Davis		
Report Date:	12 Jul 2023		

0 313

0 267

ppm

Boron


Contact/Location: Mike Clark - LIEMON





GRAPHS

 $\overline{\mathbf{O}}$



Report Id: LIEMON [WCAMIS] 02569465 (Generated: 07/12/2023 15:34:25) Rev: 1

Contact/Location: Mike Clark - LIEMON