LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH30M 139284-1253 - Diesel Engine

Sample No: LH0241859

Sulfation (PA)

Glycol

Silicon

Sodium

Potassium

Fuel

%

%

ppm

ppm

maa

63

NEG

<1.0

07

2

3

Oil Type: SHELL ROTELLA T4 15W40

Ō SAM	PLE INFO	RMATION					
Sample Number		LH0241859					
Sample Date		06 Jul 2023					
Machine Hours		1668					
Oil Hours		0					
Oil Changed		Changed					
Sample Status		NORMAL					
OILC	ONDITIO	ON					
Visc @ 100°C	cSt	13.4					
Oxidation (PA)	%	77					
CONTAMINATION							
Soot %	%	0 0					
Nitration (PA)	%	72					

1 Otaooiaiii	PPIII	<u> </u>							
WEAR METALS									
Iron	ppm	0 4							
Copper	ppm	6							
Lead	ppm	 <1							
Tin	ppm	O <1							
Aluminum	ppm	1							
Chromium	ppm	() <1							
Molybdenum	ppm	5							
Nickel	ppm	○ <1							
Titanium	ppm	<1							
Silver	ppm	0							
Manganese	ppm	○ <1							
Vanadium	ppm	0							

ADDITIVES							
Calcium	ppm	1973					
Magnesium	ppm	106					
Zinc	ppm	1100					
Phosphorus	ppm	944					
Barium	ppm	○ <1					
Boron	ppm	94					



HUBERT & FILS
474 ROUTE 105
BOIS-FRANC, QC
CA J9E 3A9
Contact: Eric Brisebois
ericbrisebois99@gmail.com
T:

F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:HUBBOIUnique No:5607569Signed:Wes DavisReport Date:18 Jul 2023

LIEBHERR







GRAPHS

