

# LIEBHERR

## CONSTRUCTION EQUIPMENT



### LIEBHERR LH30M 139284-1253 - Splitter Box

Sample No: LH0241861

Oil Type: IRVING HDH SAE 75W90



#### SAMPLE INFORMATION

Sample Number	LH0241861	---	---	---
Sample Date	07 Jun 2023	---	---	---
Machine Hours	1668	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

#### HUBERT & FILS

474 ROUTE 105  
BOIS-FRANC, QC  
CA J9E 3A9

Contact: Eric Brisebois  
ericbrisebois99@gmail.com

T:  
F:



#### OIL CONDITION

Visc @ 40°C	cSt	● 125	---	---	---
-------------	-----	-------	-----	-----	-----



#### CONTAMINATION

Silicon	ppm	● 4	---	---	---
Sodium	ppm	● 3	---	---	---
Potassium	ppm	● 2	---	---	---



#### WEAR METALS

Iron	ppm	● 63	---	---	---
Copper	ppm	● <1	---	---	---
Lead	ppm	● 0	---	---	---
Tin	ppm	● 0	---	---	---
Aluminum	ppm	● 1	---	---	---
Chromium	ppm	● <1	---	---	---
Molybdenum	ppm	● 0	---	---	---
Nickel	ppm	● <1	---	---	---
Titanium	ppm	● 0	---	---	---
Silver	ppm	● 0	---	---	---
Manganese	ppm	● 1	---	---	---
Vanadium	ppm	● 0	---	---	---



#### ADDITIVES

Calcium	ppm	● 16	---	---	---
Magnesium	ppm	● 2	---	---	---
Zinc	ppm	● 28	---	---	---
Phosphorus	ppm	● 1407	---	---	---
Barium	ppm	● 0	---	---	---
Boron	ppm	● 60	---	---	---

#### Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot: HUBBOI  
Unique No: 5607770  
Signed: Wes Davis  
Report Date: 18 Jul 2023



### GRAPHS

