

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH30M 146092-1253 - Rear Left Wheel Hub

Sample No: LH0257233

Oil Type: LIEBHERR GEAR BASIC 90 LS



9341-2906 QUEBEC INC. - Forestiers JRM Inc
491 ROUTE 381
Ferland-et-Boilleau, QC
CA G0V 1H0
Contact: Remi Simard
remisimard@hotmail.ca
T: (418)817-3634
F:



SAMPLE INFORMATION

Sample Number	LH0257233	---	---	---
Sample Date	24 Jul 2023	---	---	---
Machine Hours	950	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	64.9	---	---	---
-------------	-----	------	-----	-----	-----



CONTAMINATION

Silicon	ppm	8	---	---	---
Sodium	ppm	19	---	---	---
Potassium	ppm	<1	---	---	---



WEAR METALS

Iron	ppm	15	---	---	---
Copper	ppm	13	---	---	---
Lead	ppm	<1	---	---	---
Tin	ppm	<1	---	---	---
Aluminum	ppm	<1	---	---	---
Chromium	ppm	<1	---	---	---
Molybdenum	ppm	0	---	---	---
Nickel	ppm	<1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	3	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	3501	---	---	---
Magnesium	ppm	10	---	---	---
Zinc	ppm	1382	---	---	---
Phosphorus	ppm	1236	---	---	---
Barium	ppm	1	---	---	---
Boron	ppm	100	---	---	---

Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition. Les taux d'usure de tous les composants sont normaux. Il n'y a aucun indice de contamination dans l'huile. La viscosité de l'échantillon se situe dans la portée de l'SAE 30; nous vous conseillons de vérifier. Ceci, en plus des niveaux d'additifs, indique que la marque ou le type d'huile ne correspond pas à ce qui a été signalé. L'état de l'huile est acceptable pour la durée de service.

Depot: FOR491FER
Unique No: 5617792
Signed: Kevin Marson
Report Date: 28 Jul 2023



GRAPHS

