

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH50M 142304-1216 - Rear Right Wheel Hub

Sample No: LH

Oil Type: LIEBHERR GEAR BASIC 90 LS



PRODUITS FORESTIERS D.G. LTEE
 313 RANG ST-JOSEPH
 STE-AURELIE, QC
 CA G0M 1M0
 Contact: Roger .

T: (418)593-3547
 F: (418)593-3633



SAMPLE INFORMATION

Sample Number	LH	---	---	---
Sample Date	25 Jul 2023	---	---	---
Machine Hours	3000	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	● 187	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Silicon	ppm	● 5	---	---	---
Sodium	ppm	● 2	---	---	---
Potassium	ppm	● <1	---	---	---



WEAR METALS

Iron	ppm	● 85	---	---	---
Copper	ppm	● 16	---	---	---
Lead	ppm	● <1	---	---	---
Tin	ppm	● 0	---	---	---
Aluminum	ppm	● 1	---	---	---
Chromium	ppm	● <1	---	---	---
Molybdenum	ppm	● <1	---	---	---
Nickel	ppm	● <1	---	---	---
Titanium	ppm	● 0	---	---	---
Silver	ppm	● 0	---	---	---
Manganese	ppm	● 2	---	---	---
Vanadium	ppm	● 0	---	---	---



ADDITIVES

Calcium	ppm	● 24	---	---	---
Magnesium	ppm	● <1	---	---	---
Zinc	ppm	● 24	---	---	---
Phosphorus	ppm	● 2359	---	---	---
Barium	ppm	● 0	---	---	---
Boron	ppm	● 3	---	---	---

Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot: PRO9STE
Unique No: 5618101
Signed: Wes Davis
Report Date: 28 Jul 2023



GRAPHS

