CONSTRUCTION EQUIPMENT

[(347307)] LIEBHERR R934 052025-1550 - Swing Drive

Sample No: LH0270380

.....

Oil Type: GEAR OIL SAE 75W90

SAMPLE INFORMATION

Sample Number		LH0270380	LH0239224	LH0227478	LH0214737			
Sample Date		27 Jul 2023	15 Nov 2022	09 Mar 2022	10 Sep 2021			
Machine Hours		2892	1904	979	397			
Oil Hours		0	0	0	0			
Oil Changed		Changed	Changed	Changed	Changed			
Sample Status		ABNORMAL	ABNORMAL	ABNORMAL	ABNORMAL			
OIL CONDITION								
Visc @ 40°C	cSt	99.6	104	109	0 197			

CONTAMINATION Silicon ppm 04 6 04 3 Sodium 01 ppm \bigcirc 02 < 0 <1 Potassium ppm

A							
WEAR METALS							
PQ			0				
Iron	ppm	599	0 1043	574	327		
Copper	ppm	○ <1	◯ <1	0 1	○ <1		
Lead	ppm	○ <1	○ <1	◯ <1	○ <1		
Tin	ppm	0 🔘	0	0	0		
Aluminum	ppm	○ <1	○ <1	◯ <1	○ <1		
Chromium	ppm	08	0 13	8	6		
Molybdenum	ppm	○ <1	○ <1	◯ <1	○ <1		
Nickel	ppm	0 🔘	◯ <1	◯ <1	○ <1		
Titanium	ppm	<1	<1	0	0		
Silver	ppm	<1	0	0	<1		
Manganese	ppm	05	0 9	07	04		
Vanadium	ppm	0	<1	<1	<1		

0 **ADDITIVES** 0 13 Calcium ppm 0 14 9 0 10 Magnesium 04 2 ppm 1 \bigcirc <1 Zinc 0 13 0 13 0 15 0 12 ppm Phosphorus ppm 0 1368 0 1328 0 1385 0 1647 Barium 0 ppm $\bigcirc 0$ ○ <1 08 Boron 235 ppm 0 207 0 184 $\bigcirc 4$



MOFFATT SCRAP IRON & METAL INC.

9620 GUELPH LINE CAMPBELLVILLE, ON CA LOP 1B0 Contact: Paul Brochu maintenance@moffatscrapiron.ca T: (905)854-2792 F: (905)854-1225

Diagnosis

We advise that you check for the source of water entry. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.All component wear rates are normal. Free water present. The oil is no longer serviceable due to the presence of contaminants.

Depot:	MOFMO
Unique No:	561830
Signed:	Kevin M
Report Date:	31 Jul 2

OF 8(**Marson** 2023





GRAPHS

 \odot

