LIEBHERR

CONSTRUCTION EQUIPMENT

045705-1491 - Left Final Drive

Sample No: LH0265682

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC

TETTIC CANADA TIMOGRA 70000 CTATTLETIC						
Ō SAMF	LE INFOR	MATION				
Sample Number		LH0265682	LH0186922	LH0215203	LH0186259	
Sample Date		01 May 2023	02 Dec 2022	07 Dec 2021	11 Mar 2021	
Machine Hours		4919	3974	2976	2015	
Oil Hours		0	0	0	0	
Oil Changed		Changed	Changed	Changed	Changed	
Sample Status		NORMAL	NORMAL	ABNORMAL	ABNORMAL	
OIL CONDITION						
Visc @ 40°C	cSt	73.6	O 113	107	101	

CO	CONTAMINATION							
Silicon	ppm	10	○ 31	O 242	O 435			
Sodium	ppm	9	6 9	9	○ 37			
Potassium	nnm	1	O 3	O 16	O 33			

WEA	R METALS				
PQ				270	185
Iron	ppm	52	O 193	O 1242	1167
Copper	ppm	1	1	O 2	17
Lead	ppm	0	O <1	O <1	0 8
Tin	ppm	0	O 0	O 0	O 0
Aluminum	ppm	2	6	3 1	127
Chromium	ppm	() <1	3	O 15	<u>12</u>
Molybdenum	ppm	O <1	O <1	1	O 1
Nickel	ppm	0 <1	3	2	O 22
Titanium	ppm	<1	<1	2	7
Silver	ppm	0	0	<1	<1
Manganese	ppm	O <1	O 1	9	O 11
Vanadium	ppm	0	<1	<1	<1

vanadium	ppm	U	< 1	< 1	< 1	
ADDI						
ADDITIVES						
Calcium	ppm	16	18	O 20	O 72	
Magnesium	ppm	3	4	6	43	
Zinc	ppm	21	O 24	14	43	
Phosphorus	ppm	1283	O 1294	O 1285	O 1505	
Barium	ppm	102	1758	O 0	4	
Boron	ppm	282	○ 270	○ 204	O 190	



American Iron and Metal 1273 Kelly Lake Rd. Sudbury, ON CA P3E 5P5 Contact: Service Manager

T: F:

Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill.
Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil.
Viscosity of sample indicates oil is within SAE 80 range, advise investigate. The condition of the oil is acceptable for the time in service.

Depot:AIMSUDUnique No:5618856Signed:Wes DavisReport Date:02 Aug 2023

CONSTRUCTION EQUIPMENT





GRAPHS

