



## **UNLABELLED TOTE - New (Unused) Oil**

Sample No: LH0265568

Oil Type:

Boron

## **SAMPLE INFORMATION**

Sample Number	LH0265568	 	
Sample Date	23 Aug 2023	 	
Machine Hours	0	 	
Oil Hours	0	 	
Oil Changed	Not Changd	 	
Sample Status	ATTENTION	 	

PETRO CANADA TRAXON 75W90 SYNTHETIC

OIL CC	<b>NDITION</b>			
Visc @ 40°C	cSt	0 89.3	 	
Visc @ 100°C	cSt	0 14.3	 	
Viscosity Index (VI)	Scale	0 166	 	

CONT	'AMINATI	ON		
Silicon	ppm	<1	 	
Sodium	ppm	<b>○</b> <1	 	
Potassium	ppm	0 🔘	 	
~				
	R METALS			
WEA	K MEIALS			
Iron	ppm	<1	 	
Copper	ppm	0	 	
Lead	ppm	0	 	
Tin	ppm	0	 	
Aluminum	ppm	<1	 	
Chromium	ppm	0	 	
Molybdenum	ppm	0	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	0	 	
Vanadium	ppm	0	 	

0 **ADDITIVES** Calcium 07 ppm Magnesium 02 ppm Zinc ppm 07 Phosphorus 0 411 ppm Barium 0 ppm



## LIEBHERR CANADA LTD.

1349 KELLY LAKE RD, SUITE 5 SUDBURY, ON CA P3E 5P5 Contact: Service Manager INFO.LCA@LIEBHERR.COM T: (705)479-1066 F:

## Diagnosis

This is the baseline readout on this new (unused) oil. The fluid is suitable for service. Confirm the source of the lubricant being utilized for topup/fill.{not applicable} There is no indication of any contamination in the new (unused) oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is suitable for service.

Depot:	LIESUD
Unique No:	5631561
Signed:	Kevin Marson
Report Date:	28 Aug 2023

<mark>○</mark> <1


ppm





GRAPHS

 $\bigcirc$ 



Report Id: LIESUD [WCAMIS] 02578501 (Generated: 08/28/2023 14:44:45) Rev: 1

Contact/Location: Service Manager - LIESUD