## LIEBHERR

**CONSTRUCTION EQUIPMENT** 

### LIEBHERR R9749744 - Swing Drive

Sample No: LH0260186

Oil Type: GEAR OIL SAE 75W90

<b>5</b>				
SAM	<b>IPLE INFO</b>	RMATION		
Sample Number		LH0260186	LH0242784	 
Sample Date		03 Aug 2023	31 Jan 2023	 
Machine Hours		0	0	 
Oil Hours		0	0	 
Oil Changed		Changed	Changed	 
Sample Status		ABNORMAL	NORMAL	 
<u> </u>				
OIL	ONDITIO	N		
Visc @ 40°C	cSt	<b>105</b>	99.6	 
-44				
CON	TAMINA'	TION		
	IAMINA			
Silicon	ppm	<b>2</b>	O 2	 
Sodium	ppm	<b>2</b>	O <1	 
Potassium	ppm	<b>1</b>	<b></b> <1	 
◎ WEA				
WEA	IR METAL	.S		
Iron	ppm	<b>64</b>	<b>6</b> 5	 
Copper	ppm	<b>5</b>	<b>3</b>	 
Lead	ppm	<b>()</b> <1	O 0	 
Tin	ppm	<b>0</b>	O <1	 
Aluminum	ppm	<b>0</b> <1	O <1	 
Chromium	ppm	<b>○</b> <1	O 0	 
Molybdenum	ppm	<b>1</b>	O 0	 
Nickel	ppm	<b>0</b>	O <1	 
Titanium	ppm	0	0	 
Silver	ppm	<1	0	 
Manganese	ppm	<b>()</b> <1	O <1	 
Vanadium	ppm	0	0	 
ADD	ITIVES			
Calcium	ppm	<b>29</b>	O 2	 
Magnesium	ppm	O 22	0 1	 
Zinc	ppm	<b>33</b>	3	 
Phosphorus	ppm	<b>1086</b>	O 1546	 
Barium	ppm	0	0 0	 
_	-  -···	<u> </u>		

244





Gerdau - Mandak Metal Processors Ltd., 1 Railway St., P.O. Box 334 Selkirk, MB CA R1A 2B3 Contact: Santiago Giraldo santiago.giraldo@gerdau.com

T:

F: (204)482-8241

#### Diagnosis

We advise that you check for the source of water entry. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 75W90. Please confirm.All component wear rates are normal. There is a moderate concentration of water present in the oil. Free water present. The oil is no longer serviceable due to the presence of contaminants.

Depot:MANSELUnique No:5631964Signed:Kevin MarsonReport Date:29 Aug 2023

**139** 

ppm

Boron

# LIEBHERR

CONSTRUCTION EQUIPMENT





#### **GRAPHS**

