LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH22M 146587-1250 - Front Differential

Sample No: LH

Oil Type: NOT GIVEN

SAMPLEINFORMATION					
Sample Number	LH				
Sample Date	28 Aug 2023				
Machine Hours	574				
Oil Hours	0				
Oil Changed	N/A				
Sample Status	NORMAL				

OIL CONDITION						
Visc @ 40°C	cSt	64.8				

CONTAMINATION						
Silicon	ppm	10				
Sodium	ppm	15				
Potassium	ppm	0 <1				

WEA	R METALS	}		
Iron	ppm	21	 	
Copper	ppm	1	 	
Lead	ppm	0 0	 	
Tin	ppm	0	 	
Aluminum	ppm	1	 	
Chromium	ppm	0 <1	 	
Molybdenum	ppm	() <1	 	
Nickel	ppm	() <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	10	 	
Vanadium	ppm	0	 	

ADDITIVES						
Calcium	ppm	3565				
Magnesium	ppm	11				
Zinc	ppm	1429				
Phosphorus	ppm	1230				
Barium	ppm	() <1				
Boron	ppm	108				



CONTENEUR ROSE INC.

89 RUE MORANE LAVAL, QC CA H7M 1R5

Contact: Service Manager

T: F:

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is SAE 80 Tractor TDH Fluid. Please confirm the oil type and grade, and specify the brand of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:CON89LAVUnique No:5632226Signed:Wes DavisReport Date:29 Aug 2023

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

