

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH18M 133780-1840 - Front Left Wheel Hub

Sample No: LH0261207

Oil Type: SAE 75W90



SERVICES SANITAIRES ST-ANTOINE INC
 16600 RTE SIR WILFRID-LAURIER
 MIRABEL, QC
 CA J7J 2G3
 Contact: Service Manager



SAMPLE INFORMATION

Sample Number	LH0261207	LH0250908	---	---
Sample Date	01 Sep 2023	30 Jan 2023	---	---
Machine Hours	2973	1835	---	---
Oil Hours	0	0	---	---
Oil Changed	Changed	Changed	---	---
Sample Status	NORMAL	NORMAL	---	---



OIL CONDITION

Visc @ 40°C	cSt	151	92.3	---	---
-------------	-----	-----	------	-----	-----

T:
F:



CONTAMINATION

Silicon	ppm	3	2	---	---
Sodium	ppm	5	8	---	---
Potassium	ppm	<1	0	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	43	16	---	---
Copper	ppm	4	16	---	---
Lead	ppm	<1	<1	---	---
Tin	ppm	0	0	---	---
Aluminum	ppm	<1	<1	---	---
Chromium	ppm	<1	0	---	---
Molybdenum	ppm	0	0	---	---
Nickel	ppm	<1	<1	---	---
Titanium	ppm	0	0	---	---
Silver	ppm	0	0	---	---
Manganese	ppm	1	<1	---	---
Vanadium	ppm	0	0	---	---



ADDITIVES

Calcium	ppm	205	585	---	---
Magnesium	ppm	2	3	---	---
Zinc	ppm	47	258	---	---
Phosphorus	ppm	2132	1298	---	---
Barium	ppm	<1	0	---	---
Boron	ppm	66	252	---	---

Depot: SERMIR
 Unique No: 5633524
 Signed: Kevin Marson
 Report Date: 05 Sep 2023



GRAPHS

