## LIEBHERR

**CONSTRUCTION EQUIPMENT** 

## **LIEBHERR R920 051529-1705 - Diesel Engine**

NEG

0.5

**28** 

**5** 

**()** <1

Sample No: LH0269734
Oil Type: NOT GIVEN

%

%

ppm

ppm

ppm

Glycol

Silicon

Sodium

Potassium

Fuel

<b>A</b>						
SAMPLEINFORMATION						
Sample Number		LH0269734				
Sample Date	:	31 Aug 2023				
Machine Hours		2657				
Oil Hours		0				
Oil Changed		Changed				
Sample Status		NORMAL				
<b>A</b>						

Odifipio Otatas		HOHIWAL					
OIL CONDITION							
Visc @ 100°C	cSt	<b>12.1</b>					
Oxidation (PA)	%	83					
CONTAMINATION							
Soot %	%	<b>0</b> 0					
Nitration (PA)	%	83					
Sulfation (PA)	%	63					

<b>6</b>				
WEA	R METALS			
Iron	ppm	<b>18</b>	 	
Copper	ppm	<b>4</b>	 	
Lead	ppm	<b>0</b> <1	 	
Tin	ppm	<b>0</b>	 	
Aluminum	ppm	<b>0</b> <1	 	
Chromium	ppm	<b>0</b> <1	 	
Molybdenum	ppm	<b>59</b>	 	
Nickel	ppm	<b>0</b>	 	
Titanium	ppm	0	 	
Silver	ppm	<b>0</b>	 	
Manganese	ppm	<1	 	
Vanadium	ppm	0	 	

0						
ADDITIVES						
Calcium	ppm	<b>890</b>				
Magnesium	ppm	<b>1157</b>				
Zinc	ppm	<b>1272</b>				
Phosphorus	ppm	<b>1107</b>				
Barium	ppm	<b>0</b>				
Boron	ppm	<b>36</b>				



SHAMROCK EARTHWORKS LTD 351 EVERSYDE WAY SW CALGARY, AB CA T2Y 4R2 Contact: Service Manager

T: F:

### Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. Fuel content negligible. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:SHA351CALUnique No:5633673Signed:Wes DavisReport Date:07 Sep 2023

# LIEBHERR

### CONSTRUCTION EQUIPMENT





#### **GRAPHS**

