

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH30M 150670-1253 - Front Left Wheel Hub

Sample No: LH0271930

Oil Type: SAE 80



Gestion Transfor - Transport La Dore
 5750 Rue des Peupliers
 La Dore, QC
 CA G8J 1G4
 Contact: Eric Fortin
 efortin.transfor@hotmail.com
 T: (418)258-1182
 F: (418)256-3973



SAMPLE INFORMATION

Sample Number	LH0271930	---	---	---
Sample Date	01 Sep 2023	---	---	---
Machine Hours	458	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	65.8	---	---	---
-------------	-----	------	-----	-----	-----



CONTAMINATION

Silicon	ppm	5	---	---	---
Sodium	ppm	21	---	---	---
Potassium	ppm	1	---	---	---



WEAR METALS

Iron	ppm	56	---	---	---
Copper	ppm	23	---	---	---
Lead	ppm	<1	---	---	---
Tin	ppm	0	---	---	---
Aluminum	ppm	1	---	---	---
Chromium	ppm	<1	---	---	---
Molybdenum	ppm	0	---	---	---
Nickel	ppm	<1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	1	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	3425	---	---	---
Magnesium	ppm	10	---	---	---
Zinc	ppm	1397	---	---	---
Phosphorus	ppm	1202	---	---	---
Barium	ppm	2	---	---	---
Boron	ppm	96	---	---	---

Diagnosis

Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition. Le fluide n'était pas spécifié, toutefois, une comparaison avec d'autres fluides indiqua que ce fluide est du (GENERIC) SAE 80. Veuillez confirmer. Les taux d'usure de tous les composants sont normaux. Il n'y a aucun indice de contamination dans l'huile. L'état de l'huile est acceptable pour la durée de service.

Depot: TRALAD
 Unique No: 5642558
 Signed: Wes Davis
 Report Date: 11 Sep 2023



GRAPHS

