

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH60M 145585-1217 - Front Right Wheel Hub

Sample No: LH0259485

Oil Type: SAE 75W90



RICHMOND STEEL RECYCLING
 11760 MITCHELL ROAD
 RICHMOND, BC
 CA V6V 1V8
 Contact: Aaron Kaetler
 AKaetler@richmondsteel.ca
 T:
 F: (604)324-8617



SAMPLE INFORMATION

Sample Number	LH0259485	---	---	---
Sample Date	23 Aug 2023	---	---	---
Machine Hours	1112	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	171	---	---	---
-------------	-----	-----	-----	-----	-----



CONTAMINATION

Silicon	ppm	● <1	---	---	---
Sodium	ppm	● 3	---	---	---
Potassium	ppm	● 0	---	---	---



WEAR METALS

Iron	ppm	● 18	---	---	---
Copper	ppm	● 4	---	---	---
Lead	ppm	● 0	---	---	---
Tin	ppm	● 0	---	---	---
Aluminum	ppm	● <1	---	---	---
Chromium	ppm	● 0	---	---	---
Molybdenum	ppm	● 0	---	---	---
Nickel	ppm	● 0	---	---	---
Titanium	ppm	● 0	---	---	---
Silver	ppm	● 0	---	---	---
Manganese	ppm	● 1	---	---	---
Vanadium	ppm	● 0	---	---	---



ADDITIVES

Calcium	ppm	● 9	---	---	---
Magnesium	ppm	● 1	---	---	---
Zinc	ppm	● 13	---	---	---
Phosphorus	ppm	● 1362	---	---	---
Barium	ppm	● 262	---	---	---
Boron	ppm	● 28	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: RIC117RIC
 Unique No: 5642602
 Signed: Wes Davis
 Report Date: 12 Sep 2023



GRAPHS

