LIEBHERR



LIEBHERR LH60M 145585-1217 - Rear Left Wheel Hub

Sample No: LH0259486

ADDITIVES

ppm

ppm

ppm

ppm

ppm

ppm

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

Oil Type: GEAR OIL SAE 75W90

	<u> </u>	<u></u>	<u></u>	<u></u>
SAM	PLE INFO	PRMATION		
Sample Number		LH0259486	 	
Sample Date		23 Aug 2023	 	
Machine Hours		1112	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
<u> </u>				
OH C	ONDITIO	NA .		
Visc @ 40°C	cSt	147	 	
**				
CONT	TAMINA	TION		
Silicon		3	 	
Sodium	ppm	0 6		
Potassium	ppm	O <1		
	ppm	● <1	 	
(O)				
WEA	R META	LS		
Iron	ppm	14	 	
Copper	ppm	9	 	
Lead	ppm	0 0	 	
Tin	ppm	0	 	
Aluminum	ppm	0 <1	 	
Chromium	ppm	0 0	 	
Molybdenum	ppm	0 0	 	
Nickel	ppm	0 <1	 	
Titanium	ppm	0 0	 	
Silver	ppm	<1	 	
Manganese	ppm	0 <1	 	
Vanadium	ppm	0	 	



RICHMOND STEEL RECYCLING

11760 MITCHELL ROAD RICHMOND, BC CA V6V 1V8

Contact: Aaron Kaetler AKaetler@richmondsteel.ca

T:

F: (604)324-8617

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 75W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:RIC117RICUnique No:5642603Signed:Wes DavisReport Date:11 Sep 2023

9

2

11

99

95

1647

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

