

# LIEBHERR

## CONSTRUCTION EQUIPMENT



### LIEBHERR T33-10 022235-1695 - Splitter Box

Sample No: LH0238007

Oil Type: NOT GIVEN



#### SAMPLE INFORMATION

Sample Number	LH0238007	---	---	---
Sample Date	26 Aug 2023	---	---	---
Machine Hours	2029	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

**NOVA TREE SEED COMPANY INC**  
 2715 HIGHWAY 4  
 DEBERT, NS  
 CA B0M 1G0  
 Contact: Service Manager



#### OIL CONDITION

Visc @ 40°C	cSt	44.6	---	---	---
-------------	-----	------	-----	-----	-----

T:  
F:



#### CONTAMINATION

Silicon	ppm	2	---	---	---
Sodium	ppm	1	---	---	---
Potassium	ppm	1	---	---	---

#### Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



#### WEAR METALS

Iron	ppm	11	---	---	---
Copper	ppm	4	---	---	---
Lead	ppm	2	---	---	---
Tin	ppm	0	---	---	---
Aluminum	ppm	<1	---	---	---
Chromium	ppm	<1	---	---	---
Molybdenum	ppm	<1	---	---	---
Nickel	ppm	<1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	<1	---	---	---
Vanadium	ppm	0	---	---	---



#### ADDITIVES

Calcium	ppm	1177	---	---	---
Magnesium	ppm	7	---	---	---
Zinc	ppm	623	---	---	---
Phosphorus	ppm	619	---	---	---
Barium	ppm	0	---	---	---
Boron	ppm	2	---	---	---

Depot: NOVDEB  
 Unique No: 5643304  
 Signed: Kevin Marson  
 Report Date: 14 Sep 2023



### GRAPHS

