LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR L556 065678-1826 - Splitter Box

Sample No: LH0232594

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC

SAMPLE INFORMATION						
Sample Number	LH0232594	LH	LH0239135			
Sample Date	31 Jul 2023	26 Apr 2023	29 Aug 2022			
Machine Hours	3914	3418	1292			
Oil Hours	0	0	0			
Oil Changed	Changed	N/A	Changed			
Sample Status	NORMAL	SEVERE	NORMAL			

ouripio otatas	HOHIMAL	OLVLILL	TAOT TIVIT TE	
OIL CONDITION	N			
Visc @ 40°C cSt	166	O 111	93.5	
-1				

CONT	AMINATIO	ON			
Silicon	ppm	1	3	O 4	
Sodium	ppm	1	6	3	
Potassium	ppm	() <1	 <1	○ <1	

WEAR METALS						
PQ			O 0			
Iron	ppm	55	446	84		
Copper	ppm	1	O 2	O <1		
Lead	ppm	1	O <1	O <1		
Tin	ppm	0	0	0		
Aluminum	ppm	0 <1	O 2	O <1		
Chromium	ppm	() <1	4	O <1		
Molybdenum	ppm	() <1	O <1	O <1		
Nickel	ppm	() <1	O 2	1		
Titanium	ppm	0	<1	0		
Silver	ppm	0	0	0		
Manganese	ppm	1	7	O 1		
Vanadium	ppm	0	0	0		

ADD	ITIVES				
Calcium	ppm	11	O 13	9	
Magnesium	ppm	6	O 10	4	
Zinc	ppm	183	1844	45	
Phosphorus	ppm	2934	8371	2660	
Barium	ppm	0	O 0	5	
Boron	ppm	5	38	137	



BOIS LIB INC. 275 RUE JEREMIE-PACAUD PRINCEVILLE, QC CA G6L 0A1

Contact: Service Manager

T: F:

Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill.
Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. Viscosity of sample indicates oil is within SAE 90 range, advise investigate. This plus the additive levels indicates that this is not the same brand, or type of oil as reported. The condition of the oil is acceptable for the time in service.

Depot: LIBPRI
Unique No: 5643650
Signed: Kevin Marson
Report Date: 15 Sep 2023





GRAPHS

