LIEBHERR

0

N/A

CONSTRUCTION EQUIPMENT

056328-1783-Splitter Box

Oil Hours

Oil Changed



Sample Status		NORMAL					
OIL CONDITION							
Visc @ 40°C	cSt	170					

CONTAMINATION						
Silicon	ppm	1				
Sodium	ppm	2				
Potassium	ppm	1				

WEA	R METALS	5		
Iron	ppm	○ 30	 	
Copper	ppm	2	 	
Lead	ppm	0	 	
Tin	ppm	0	 	
Aluminum	ppm	0 <1	 	
Chromium	ppm	4	 	
Molybdenum	ppm	0	 	
Nickel	ppm	2	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	3	 	
Vanadium	ppm	0	 	

ADDITIVES					
Calcium	ppm	33			
Magnesium	ppm	() <1			
Zinc	ppm	39			
Phosphorus	ppm	2114			
Barium	ppm	() <1			
Boron	ppm	1			





American Iron and Metal

10305 Metropolitaine Est, Garage porte 13 Montreal, QC CA H1B 1A1

Contact: Sebastien Liautaud sliautaud@aimrecyclinggroup.com

T: F:

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:LACMONUnique No:5644736Signed:Wes DavisReport Date:19 Sep 2023

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

