LIEBHERR

CONSTRUCTION EQUIPMENT



Sample No: LH0260553

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC

a				
U SAN	APLE INF	ORMATION		
Sample Number		LH0260553	LH0226447	
Sample Date		12 Sep 2023	13 Feb 2023	
Machine Hours		4272	2833	
Oil Hours		0	0	
Oil Changed		Changed	Changed	
Sample Status		NORMAL	ABNORMAL	
OIL	CONDITI	ON		
Visc @ 40°C	cSt	92.8	O 64.4	
- A				
CON	ITAMIN/	ATION		
Silicon	ppm	2	O 4	
Sodium	ppm	5	O 14	
Potassium	ppm	() <1	O 2	
WE/	AR META	LS		
lvon	10.100.000	O 00	O 10	

WEA	R METAL	.S		
Iron	ppm	20	O 40	
Copper	ppm	13	O 21	
Lead	ppm	<1	O <1	
Tin	ppm	0	<1	
Aluminum	ppm	<1	O <1	
Chromium	ppm	0	O <1	
Molybdenum	ppm	0	0	
Nickel	ppm	0	0	
Titanium	ppm	0	<1	
Silver	ppm	0	0	
Manganese	ppm	<1	O <1	
Vanadium	ppm	0	0	

ADDITIVES								
Calcium	ppm	883	3623					
Magnesium	ppm	4	9					
Zinc	ppm	374	1416					
Phosphorus	ppm	1234	1227					
Barium	ppm	○ <1	O 1					
Boron	ppm	218	101					



West Coast Metal Recycling

5771 Production Way Langley, BC CA V3A 4N5 Contact: Terry . terry@gotmetal.ca

T: F:

Diagnosis

being utilized for top-up/fill. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Confirm the source of the lubricant

Depot: WES577LAN
Unique No: 5645180
Signed: Bill Quesnel
Report Date: 21 Sep 2023

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

