LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR L580 069050-1760 - Rear Right Wheel Hub

Sample No: LH0240414

Oil Type: LIEBHERR GEAR BASIC 90 LS

Ō CAM						
SAM	PLE INFOR	MATION				
Sample Number		LH0240414	LH0240392	LH0240381		
Sample Date		15 Sep 2023	04 Mar 2023	13 Dec 2022		
Machine Hours		4000	2000	1005		
Oil Hours		0	0	0		
Oil Changed		Changed	Changed	Changed		
Sample Status		NORMAL	NORMAL	NORMAL		
A						
OIL CONDITION						
Visc @ 40°C	cSt	O 184	O 182	193		

	OIL CC	NDITION					
isc @	40°C	cSt	184	O 182	193		
4							
CONTAMINATION							
			O 10	0.0	000		

CONTAMINATION							
Silicon	ppm	10	6	O 29			
Sodium	ppm	4	O <1	6			
Potassium	ppm	2	O <1	O 2			

WEA	R METAL	S			
Iron	ppm	143	O 50	○ 252	
Copper	ppm	100	74	206	
Lead	ppm	3	0 2	5	
Tin	ppm	9	4	12	
Aluminum	ppm	 <1	O <1	02	
Chromium	ppm	○ <1	O <1	0 2	
Molybdenum	ppm	 <1	O 0	O	
Nickel	ppm	○ <1	O <1	02	
Titanium	ppm	0	0	<1	
Silver	ppm	<1	0	0	
Manganese	ppm	7	6	58	
Vanadium	ppm	0	0	<1	

ADDITIVES							
Calcium	ppm	13	6	9			
Magnesium	ppm	12	3	3			
Zinc	ppm	155	25	64			
Phosphorus	ppm	2428	2493	2351			
Barium	ppm	0	O 0	O			
Boron	ppm	1	O <1	O 2			



PRODUITS FORESTIERS D.G. LTEE 313 RANG ST-JOSEPH

STE-AURELIE, QC CA G0M 1M0 Contact: Roger.

T: (418)593-3547 F: (418)593-3633

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:PRO9STEUnique No:5645568Signed:Bill QuesnelReport Date:21 Sep 2023





GRAPHS

