LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR L580 069050-1760 - Rear Differential

Sample No: LH0240406

ADDITIVES

ppm

ppm

ppm

ppm

ppm

ppm

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

Oil Type: LIEBHERR GEAR BASIC 90 LS

SAM	PLE INFO	DRMATION			
Sample Number		LH0240406	LH0240384	LH0240373	
Sample Date		15 Sep 2023	04 Mar 2023	13 Dec 2022	
Machine Hours		4000	2000	1005	
Oil Hours		0	0	0	
Oil Changed		Changed	Changed	Changed	
Sample Status		NORMAL	NORMAL	NORMAL	
OIL	ONDITIO	ON			
Visc @ 40°C	cSt	183	O 182	O 194	
-4-					
CON	TAMINA	TION			
Silicon	ppm	11	6	O 29	
Sodium	ppm	3	O 1	6	
Potassium	ppm	0	O 0	1	
◎ WEA	R META				
lron	ppm	143	O 50	O 256	
Copper	ppm	100	O 74	206	
_ead	ppm	3	O 2	O 6	
Tin	ppm	9	O 4	13	
Aluminum	ppm	O <1	O <1	O 2	
Chromium	ppm	○ <1	O <1	3	
Molybdenum	ppm	() <1	O 0	O 0	
Nickel	ppm	() <1	O <1	O 2	
Titanium	ppm	0	O 0	<1 <1	
Silver	ppm	0	0	0	
Manganese	ppm	7	6	58	
Vanadium	ppm	0	0	<1	
THE STATE OF THE S					

0 6

 \bigcirc 3

0

25

2531

10

 \bigcirc 3

64

 \bigcirc 0

 \bigcirc 2

2365



PRODUITS FORESTIERS D.G. LTEE

313 RANG ST-JOSEPH STE-AURELIE, QC CA G0M 1M0 Contact: Roger.

T: (418)593-3547 F: (418)593-3633

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:PRO9STEUnique No:5645581Signed:Bill QuesnelReport Date:22 Sep 2023

13

11

155

2426

0

<1</p>





GRAPHS

