LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH50 138422 - Rear Left Wheel Hub

Sample No: LH0270225

Oil Type: GEAR OIL SAE 75W90

CAN				
SAM	PLE INFO	RMATION		
Sample Number		LH0270225	 	
Sample Date		12 Oct 2023	 	
Machine Hours		4805	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
OIL C	ONDITIO	N		
Visc @ 40°C	cSt	104	 	
V13C @ +0 O	COL	0 104		
CON	TAMINA	rion		
Silicon	ppm	12	 	
Sodium	ppm	2	 	
Potassium	ppm	0 <1	 	
**				
◎ WEA	R METAL	C		
		- Taragaran -		
Iron	ppm	7	 	
Copper	ppm	0 10	 	
Lead	ppm	0 <1	 	
Tin	ppm	0 0	 	
Aluminum	ppm	0 <1	 	
Chromium	ppm	0 0	 	
Molybdenum	ppm	0 0	 	
Nickel	ppm	O <1	 	
Titanium	ppm	0	 	
Silver	ppm	<1	 	
Manganese	ppm	0	 	
Vanadium	ppm	0	 	
ADDI	TIVES			
Calcium	ppm	10	 	
Magnesium	ppm	O <1	 	
Zinc	ppm	14	 	
	1.15	<u> </u>		



LIEBHERR CANADA LTD.

1015 SUTTON DRIVE BURLINGTON, ON CA L7L 5Z8

Contact: Steve Lehto steve.lehto@liebherr.com

T: (905)319-9222 F: (905)319-6617

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 75W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: LIEMIS
Unique No: 5658081
Signed: Wes Davis
Report Date: 13 Oct 2023

Contact/Location: Steve Lehto - LIEMIS

1217

<1</p>

312

Phosphorus

Barium

Boron

ppm

ppm

ppm

LIEBHERR







GRAPHS

