

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH50 37429 - Front Right Wheel Hub

Sample No: LH0277641

Oil Type: NOT GIVEN



LIEBHERR CANADA LTD.
 1015 SUTTON DRIVE
 BURLINGTON, ON
 CA L7L 5Z8
 Contact: Joseph Rodgers
 joseph.rodgers@liebherr.com
 T: (905)319-9222
 F: (905)319-6622



SAMPLE INFORMATION

Sample Number	LH0277641	---	---	---
Sample Date	12 Oct 2023	---	---	---
Machine Hours	6950	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	● 101	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Silicon	ppm	● 2	---	---	---
Sodium	ppm	● 3	---	---	---
Potassium	ppm	● 1	---	---	---



WEAR METALS

Iron	ppm	● 16	---	---	---
Copper	ppm	● 51	---	---	---
Lead	ppm	● 1	---	---	---
Tin	ppm	● 0	---	---	---
Aluminum	ppm	● 2	---	---	---
Chromium	ppm	● 0	---	---	---
Molybdenum	ppm	0	---	---	---
Nickel	ppm	● <1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	<1	---	---	---
Manganese	ppm	2	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	37	---	---	---
Magnesium	ppm	1	---	---	---
Zinc	ppm	47	---	---	---
Phosphorus	ppm	1238	---	---	---
Barium	ppm	<1	---	---	---
Boron	ppm	308	---	---	---

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is SAE 75W90 Gear Oil. Please confirm the oil type and grade, and specify the brand of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: LIEMIS
 Unique No: 5658084
 Signed: Wes Davis
 Report Date: 16 Oct 2023



GRAPHS

