LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH30M 139284-1253 - Rear Left Wheel Hub

Sample No: LH0239959

Silver

Manganese

Vanadium

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

ppm

ppm

ppm

ppm

ppm

ppm

ppm

ppm

ppm

ADDITIVES

<1

0

29

<1</p>

8

<1</p>

5

2247

Oil Type: LIEBHERR GEAR BASIC 90 LS

5					
SAM	PLE INFO	DRMATION			
Sample Number		LH0239959	LH0208259	LH0241866	
Sample Date		04 Sep 2023	06 Jul 2023	18 Apr 2023	
Machine Hours		2265	1668	1142	
Oil Hours		0	0	0	
Oil Changed		Changed	Changed	Changed	
Sample Status		NORMAL	NORMAL	NORMAL	
OIL	ONDITIO	N			
Visc @ 40°C	cSt	179	O 175	99.9	
_L			0		
CON		TIAN			
CON	TAMINA	IION			
Silicon	ppm	0 <1	0 2	O <1	
Sodium	ppm	2	O 2	O 1	
Potassium	ppm	0	O <1	O <1	
WEA	R META	LS			
Iron	ppm	6	O 7	O 3	
Copper	ppm	01	O <1	0 1	
Lead	ppm	0 0	0 0	0 0	
Tin	ppm	0	0	0	
Aluminum	ppm	0 <1	O <1	0	
Chromium	ppm	0 0	0 0	0	
Molybdenum	ppm	0 0	0 0	0	
Nickel	ppm	0 <1	0 <1	0 <1	
Titanium	ppm	0	0	0	

97

32

2282

154

157

1302

 \bigcirc <1



HUBERT & FILS 474 ROUTE 105 BOIS-FRANC, QC CA J9E 3A9 Contact: Eric Brisebois ericbrisebois99@gmail.com

T: F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:HUBBOIUnique No:5659443Signed:Wes DavisReport Date:19 Oct 2023

LIEBHERR







GRAPHS

